

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 21.12.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SNF5082H
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 21.12.2022
TIME OF ACCIDENT : 13:15 HRS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER Distorted	1	\$ 865.50	\$ 865.50
2	REAR BUMPER REFLECTOR RH cracked	2	\$ 151.10	\$ 302.20
3	REAR BUMPER SIDE RH cracked	2	\$ 230.00	\$ 460.00
4	REAR BUMPER SIDE RETAINER New	2	\$ 57.00	\$ 114.00
5	REAR FENDER INNER TRIM RH cracked	2	\$ 399.10	\$ 798.20
6	REAR FENDER COWLING New	2	\$ 150.20	\$ 300.40
7	REAR FENDER ARCED GARNISH RH torn	2	\$ 184.70	\$ 369.40
8	TAIL LAMP RH cracked	2	\$ 475.00	\$ 950.00
9	TAILGATE Distorted	1	\$ 1,420.00	\$ 1,420.00
10	TAILGATE LOGO New	1	\$ 65.00	\$ 65.00
11	TAILGATE OUTER GARNISH New	1	\$ 220.00	\$ 220.00
12	TAILGATE SIDE LAMP RH cracked	2	\$ 240.00	\$ 480.00
13	TAILGATE DAMPER New	2	\$ 186.00	\$ 372.00
14	TAILGATE INNER HOLDER New	1	\$ 52.00	\$ 52.00
15	TAILGATE STOPPER New	2	\$ 19.00	\$ 38.00
16	TAILGATE TOP LOCK New	1	\$ 180.00	\$ 180.00
17	TAILGATE LOWER LOCK New	1	\$ 24.70	\$ 24.70
18	TAILGATE INNER TRIM Cracked	1	\$ 398.60	\$ 398.60
19	TAILGATE LOCK CONNECTOR New cracked	1	\$ 379.00	\$ 379.00
20	TAILGATE WEATHER STRIP New	1	\$ 168.40	\$ 168.40
21	TAILGATE WINDSCREEN MOULDING (SET) New	1	\$ 164.00	\$ 164.00

745
151.10
230
+
399.10
+
184.70
475
1100
+
+
240
+
+
+
+
298
150
✓
✓

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SNF5082H
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 21.12.2022
 TIME OF ACCIDENT : 13:15 HRS

22	BUZZER <i>New</i>	1	\$ 109.00	\$ 109.00	+
23	REAR END PANEL <i>Dented</i>	1	\$ 530.00	\$ 530.00	✓
24	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 146.30	\$ 146.30	✓
25	REAR FLOOR PANEL <i>Rips</i>	1	\$ 1,130.00	\$ 1,130.00	+
26	REAR FLOOR PANEL BOTTOM GARNISH <i>Dented</i>	1	\$ 269.00	\$ 269.00	✓
27	REAR FLOOR PANEL TOP BOARD <i>New Dented</i>	1	\$ 300.40	\$ 300.40	✓
28	REAR STORAGE BOX <i>Cracked</i>	1	\$ 495.00	\$ 495.00	295
29	REAR CHASSIS MEMBER RH <i>New</i>	1	\$ 797.40	\$ 797.40	+
30	REAR EXHAUST INSULATOR <i>New</i>	1	\$ 155.00	\$ 155.00	+
31	REAR EXHAUST PIPE <i>Best</i>	1	\$ 980.00	\$ <u>980.00</u>	598
32	REAR EXHAUST MOUNTING <i>New</i>	4	\$ 18.00	\$ 72.00	+
33	REAR EXHAUST GASKET (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	45

6489
519120

TOTAL PRICE \$ 13,185.50
 LESS 20% \$ 2,637.10
 SUB TOTAL PRICE \$ 10,548.40

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	30
2	REAR BUMPER CHROME MOULDING (SPECAIL TYPE)	1	\$ 350.00	\$ 350.00	150
3	TAILGATE SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	+
4	TAILGATE OUTER GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
5	TAILGATE INNER TRIM BOARD CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	30
6	TAILGATE WINDSCREEN SEALANT <i>3/4 New</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
8	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	10
9	REAR FENDER INNER TRIM CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	30
10	REAR FENDER COWLING CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
11	REAR FENDER ARCDED GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	20
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	20
13	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	60
14	REAR FLOOR PANEL SEALANT <i>New</i>	1	\$ 350.00	\$ 350.00	+
15	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	30
16	REAR FLOOR TOWING PANEL SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	+
17	REAR EXHAUST CHROME PIPE <i>New</i>	1	\$ 180.00	\$ 180.00	+

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SNF5082H
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 21.12.2022
 TIME OF ACCIDENT : 13:15 HRS

18	REVERSE CAMERA <i>Not Rec</i>	1	\$ 550.00	\$ 550.00	<i>+</i>
19	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 250.00	\$ 250.00	<i>2w</i>

650

TOTAL \$ 2,680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>8w</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>8w</i>
3	TUFF COAT	\$ 250.00	<i>6w</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>6w</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>5w</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>5w</i>
7	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	<i>5w</i>
8	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>x</i>
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	<i>12w</i>
11	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>6w</i>
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>8w</i>
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	<i>x</i>

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNF5082H**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 21.12.2022
 TIME OF ACCIDENT : 13:15 HRS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,360.00

TOTAL PARTS COST : \$ 13,228.40
 TOTAL LABOUR COST : \$ 5,360.00
 TOTAL REPAIR COST : \$ 18,588.40

2130

Adrian G
2/s 22/12/22.
06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 7971.20

c/s: 6350 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: