

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Xiao Chen.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 8107 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 500	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	?
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00 500. +1250.	88/8.
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS.	\$ 3,500.00 550	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,872.00	

** Additional 3 working days.*

for the replacement of

Lock carrier

Adrian King

Car-in

6/2/23

wp: 55687

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AKA - 1/4 day
- 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS ne m	1	\$ 612.00	X.
3	FRONT BUMPER SECURING STRIP - LH / RH ne m	2	\$ 79.00	+
4	FRONT BUMPER GRILLE - CENTER canld	1	\$ 219.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ne m	1	\$ 254.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH ne m	2	\$ 144.00	+
7	RADIATOR GRILLE canld	1	\$ 1,478.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH xhol m	2	\$ 302.00	+
9	FRONT BUMPER FOAM FILLER PIECE canld	1	\$ 139.00	✓
10	FRONT BUMPER REINFORCEMENT BEAM Distorted	1	\$ 899.00	✓
11	FRONT BUMPER BRACKET (LH) RH 2H Bent.	2	\$ 508.00	254. H.S.
12	FRONT BUMPER GUIDE SECTION - LH / RH ne m	2	\$ 82.00	+
13	FRONT BUMPER TOP COVER canld	1	\$ 143.00	✓
14	CAUTION SIGN STICKER } over	1	\$ 16.00	✓
15	AIR CONDITIONER STICKER	1	\$ 9.00	✓
16	FRONT BUMPER BRACKET Dmgd.	1	\$ 154.00	✓ H.S.
17	FRONT BUMPER SUPPORT (LH) RH Dmgd.	2	\$ 64.00	✓ H.S.
18	HORN HIGH TONE - LH } ne m	1	\$ 134.00	+
19	HORN LOW TONE - RH	1	\$ 139.00	+
20	HORN BRACKET - LH / RH ne m	2	\$ 66.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,818.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET BOWDEN CABLE - CENTER	1 S	64.00	✓
42	BONNET RELEASE CABLE COVER	1 S	11.00	✓
43	BONNET BOWDEN CABLE	1 S	64.00	✓
44	BONNET RELEASE LEVER	1 S	15.00	✓
(photo) 45	HEADLIGHT - LH / RH <i>cracked</i>	2 S	16,588.00	✓
46	LIFT CYLINDER - LH / RH	2 S	462.00	+
47	LIFT CYLINDER BRACKET - LH / RH	2 S	14.00	+
48	LIFT CYLINDER CORRUGATED PIPE	1 S	107.00	+
49	LOCK CARRIER <i>cracked</i>	1 S	1,478.00	✓ <i>sl.s.</i>
50	LOCK CARRIER SUPPORT - LH / RH	2 S	85.00	?
51	A/C CONDENSER <i>Dented</i>	1 S	683.00	✓
52	A/C CONDENSER REFRIGERANT LINE	1 S	186.00	+
53	A/C CONDENSER REFRIGERANT LINE	1 S	381.00	+
54	A/C CONDENSER REFRIGERANT LINE	1 S	277.00	+
55	OUTSIDE TEMPERATURE SENSOR BRACKET <i>re new</i>	1 S	21.00	✓ <i>sl.s.</i>
56	CHARGE AIR COOLER <i>re new</i>	1 S	654.00	+
57	CHARGE AIR COOLER PRESSURE PIPE <i>re new</i>	1 S	496.00	+
58	CHARGE AIR COOLER PRESSURE HOSE	1 S	413.00	+
59	RADIATOR <i>re new</i>	1 S	1,013.00	+
60	READY-MIX COOLANT <i>re new</i>	6 S	297.00	✓
SUB TOTAL SPARE PARTS		:	\$ 23,309.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	RADIATOR AIR GUIDE LH RH INNER {Dangd.	2	\$ 64.00	✓	
62	RADIATOR AIR GUIDE LH RH OUTER {Dangd.	2	\$ 28.00	✓	
63	RADIATOR AIR GUIDE - UPPER / LOWER neu	2	\$ 44.00	+	
64	RADIATOR FAN RING neu	1	\$ 292.00	+	
65	RADIATOR FAN CONTROL UNIT neu	1	\$ 2,489.00	+	
66	INTAKE AIR DUCT - RH LOWER neu	1	\$ 25.00	+	
67	ENGINE AIR INTAKE HOSE - CENTER neu	1	\$ 61.00	+	
68	FRONT NO PLATE Bent	S/N	\$ 60.00	✓	
69	SUNDRIES ?		\$ 500.00	>	
TOTAL SPARE PARTS		:	\$ 44,026.00		
TOTAL LABOUR CHARGES		:	\$ 11,872.00		
GRAND TOTAL		:	\$ 55,898.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.