

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1139/2022/EQ
DATE : 20-Dec-22
WIP : 55687

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

8 days exclude 1 Sunday

Johnny Boo 13 Mar 22

OWNER'S NAME : MR ANTONIO FERACO
ADDRESS : 19 KEPPEL BAY VIEW
#06-61
SINGAPORE 098412
TELEPHONE : HP +65 90080639
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 190090612-01
VEHICLE NO : **SMK 8107 L**
MODEL CODE : AUDI A4 AVANT 2.0 TFSI S
MODEL YEAR : 25/4/2019
ENGINE NO : CVK 078394
CHASSIS NO : WAUZZZF4XKA050426
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Dec-22
PLACE OF ACCIDENT : CTE, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 8107 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	\$	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. (A4 2 ltr - LC x 3 days)	\$	5,600.00	\$	2,000.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS.	\$	3,500.00	\$	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 11,872.00	\$	5,122.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	\$ 1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 144.00	
7	RADIATOR GRILLE	1	\$ 1,478.00	\$ 1,182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	\$ 110.80
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	\$ 719.20
11	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00	\$ 203.20
12	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	
13	FRONT BUMPER TOP COVER	1	\$ 143.00	\$ 114.00
14	CAUTION SIGN STICKER	1	\$ 16.00	\$ 12.40
15	AIR CONDITIONER STICKER	1	\$ 9.00	\$ 6.64
16	FRONT BUMPER BRACKET	1	\$ 154.00	\$ 122.80
17	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	\$ 51.04
18	HORN HIGH TONE - LH	1	\$ 134.00	
19	HORN LOW TONE - RH	1	\$ 139.00	
20	HORN BRACKET - LH / RH	2	\$ 66.00	
SUB TOTAL SPARE PARTS		:	\$ 7,818.00	\$ 4,598.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f	\$	
21	FRONT PARKING AID SENSOR - INNER / OUTER	4	\$ 1,062.00	
22	FRONT PARKING AID SEAL RING	4	\$ 10.00	
23	FRONT BUMPER WIRING SET	1	\$ 567.00	
24	FRONT FENDER - LH / RH	2	\$ 1,722.00	
25	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00	
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 162.00	
27	FRONT FENDER BRACKET - LH / RH	2	\$ 82.00	
28	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH	2	\$ 110.00	
29	FRONT FENDER RIVET	12	\$ 46.00	
30	FRONT FENDER BRACE - LH / RH	2	\$ 264.00	
31	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 522.00	
32	FRONT WHEEL SPOILER - LH / RH	2	\$ 164.00	
33	FRONT WHEEL SPOILER END PLATE - LH / RH	2	\$ 79.00	
34	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH	2	\$ 114.00	
35	FRONT FENDER LEDGE COVER - LH / RH LONG	2	\$ 70.00	
36	FRONT FENDER LEDGE COVER - LH / RH SHORT	2	\$ 52.00	
37	BONNET	1	\$ 3,425.00	
38	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	
39	BONNET STRIKER - LH / RH	2	\$ 112.00	
40	BONNET LOCK - LH / RH	2	\$ 455.00	
SUB TOTAL SPARE PARTS		:	\$ 9,336.00	\$ 4,598.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 4,598.88
41	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	
42	BONNET RELEASE CABLE COVER	1	\$ 11.00	
43	BONNET BOWDEN CABLE	1	\$ 64.00	
44	BONNET RELEASE LEVER	1	\$ 15.00	
45	HEADLIGHT - LH / RH	2	\$ 16,588.00	\$ 13,270.40
46	LIFT CYLINDER - LH / RH	2	\$ 462.00	
47	LIFT CYLINDER BRACKET - LH / RH	2	\$ 14.00	
48	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
49	LOCK CARRIER	1	\$ 1,478.00	\$ 901.60
50	LOCK CARRIER SUPPORT - LH / RH	2	\$ 85.00	
51	A/C CONDENSER	1	\$ 683.00	\$ 546.00
52	A/C CONDENSER REFRIGERANT LINE	1	\$ 186.00	
53	A/C CONDENSER REFRIGERANT LINE	1	\$ 381.00	
54	A/C CONDENSER REFRIGERANT LINE	1	\$ 277.00	
55	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	\$ 16.32
56	CHARGE AIR COOLER	1	\$ 654.00	
57	CHARGE AIR COOLER PRESSURE PIPE	1	\$ 496.00	
58	CHARGE AIR COOLER PRESSURE HOSE	1	\$ 413.00	
59	RADIATOR	1	\$ 1,013.00	
60	READY-MIX COOLANT	6	\$ 297.00	\$ 237.12
SUB TOTAL SPARE PARTS		:	\$ 23,309.00	\$ 19,570.32

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	19,570.32
61	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 64.00	\$	51.20
62	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 28.00	\$	21.76
63	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00		
64	RADIATOR FAN RING	1	\$ 292.00		
65	RADIATOR FAN CONTROL UNIT	1	\$ 2,489.00		
66	INTAKE AIR DUCT - RH LOWER	1	\$ 25.00		
67	ENGINE AIR INTAKE HOSE - CENTER	1	\$ 61.00		
68	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
69	SUNDRIES		\$ 500.00	\$	2.88
TOTAL SPARE PARTS		:	\$ 44,026.00	\$	19,706.16
TOTAL LABOUR CHARGES		:	\$ 11,872.00	\$	5,122.00
GRAND TOTAL		:	\$ 55,898.00	\$	24,828.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-22/02/23

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT