

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1139/2022/EQ
DATE : 20-Dec-22
WIP : 55687

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ANTONIO FERACO
ADDRESS : 19 KEPPEL BAY VIEW
#06-61
SINGAPORE 098412
TELEPHONE : HP +65 90080639
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 190090612-01
VEHICLE NO : **SMK 8107 L**
MODEL CODE : AUDI A4 AVANT 2.0 TFSI S
MODEL YEAR : 25/4/2019
ENGINE NO : CVK 078394
CHASSIS NO : WAUZZZF4XKA050426
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Dec-22
PLACE OF ACCIDENT : CTE, SINGAPORE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Xiao Chen.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 8107 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	700.00 500	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. S/N \$	1,400.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. S/N \$	5,600.00 7000	500. +1250.
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS. S/N \$	3,500.00	550/
6	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,872.00	

* Additional 3 working days.

for the replacement of

Lock carrier

Adrian King

Car-in

6/2/23

wp: 55687

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AKA - 1/2/23
- 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1	\$ 2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS ne m	1	\$ 612.00	X.
3	FRONT BUMPER SECURING STRIP - LH / RH ne m	2	\$ 79.00	+
4	FRONT BUMPER GRILLE - CENTER canld	1	\$ 219.00	✓ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ne m	1	\$ 254.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH ne m	2	\$ 144.00	+
7	RADIATOR GRILLE canld	1	\$ 1,478.00	✓ 1182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH xhol m	2	\$ 302.00	+
9	FRONT BUMPER FOAM FILLER PIECE canld	1	\$ 139.00	✓ 110.80
10	FRONT BUMPER REINFORCEMENT BEAM Distorted	1	\$ 899.00	✓ 719.20
11	FRONT BUMPER BRACKET (LH) RH 2H Bent.	2	\$ 508.00	203.20 ✓ 254. fls.
12	FRONT BUMPER GUIDE SECTION - LH / RH ne m	2	\$ 82.00	+
13	FRONT BUMPER TOP COVER canld	1	\$ 143.00	✓ 114
14	CAUTION SIGN STICKER } ne m	1	\$ 16.00	✓ 12.80
15	AIR CONDITIONER STICKER	1	\$ 9.00	✓ 6.64 fls.
16	FRONT BUMPER BRACKET Dmg d.	1	\$ 154.00	122.80 ✓ fls.
17	FRONT BUMPER SUPPORT (LH) RH Dmg d.	2	\$ 64.00	51.04 ✓ fls.
18	HORN HIGH TONE - LH } ne m	1	\$ 134.00	+
19	HORN LOW TONE - RH	1	\$ 139.00	+
20	HORN BRACKET - LH / RH ne m	2	\$ 66.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,818.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	4	\$ 1,062.00	+
22	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 10.00	+
23	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 567.00	+
24	FRONT FENDER - LH / RH <i>new</i>	2	\$ 1,722.00	+
25	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 225.00	+
26	FRONT FENDER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 162.00	+
27	FRONT FENDER BRACKET - LH / RH <i>new</i>	2	\$ 82.00	+
28	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH	2	\$ 110.00	+
29	FRONT FENDER RIVET <i>new</i>	12	\$ 46.00	+
30	FRONT FENDER BRACE - LH / RH <i>new</i>	2	\$ 264.00	+
31	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 522.00	+
32	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 164.00	+
33	FRONT WHEEL SPOILER END PLATE - LH / RH <i>new</i>	2	\$ 79.00	+
34	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH <i>new</i>	2	\$ 114.00	+
35	FRONT FENDER LEDGE COVER - LH / RH LONG <i>new</i>	2	\$ 70.00	+
36	FRONT FENDER LEDGE COVER - LH / RH SHORT <i>new</i>	2	\$ 52.00	+
37	BONNET <i>new</i>	1	\$ 3,425.00	+
38	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$ 93.00	+
39	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 112.00	+
40	BONNET LOCK - LH / RH <i>new</i>	2	\$ 455.00	+
SUB TOTAL SPARE PARTS		:	\$ 9,336.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST


LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET BOWDEN CABLE - CENTER	1 S	64.00	+
42	BONNET RELEASE CABLE COVER	1 S	11.00	+
43	BONNET BOWDEN CABLE	1 S	64.00	+
44	BONNET RELEASE LEVER	1 S	15.00	+
(photo) 45	HEADLIGHT - LH / RH <i>cracked</i>	2 S	16,588.00	✓ 13270.40
46	LIFT CYLINDER - LH / RH	2 S	462.00	+
47	LIFT CYLINDER BRACKET - LH / RH	2 S	14.00	+
48	LIFT CYLINDER CORRUGATED PIPE	1 S	107.00	+
49	LOCK CARRIER <i>cracked</i>	1 S	901.60	1,478.00 ✓ <i>sls.</i>
50	LOCK CARRIER SUPPORT - LH / RH <i>new</i>	2 S	85.00	✗
51	A/C CONDENSER <i>Dented</i>	1 S	683.00	✓ 546
52	A/C CONDENSER REFRIGERANT LINE	1 S	186.00	+
53	A/C CONDENSER REFRIGERANT LINE	1 S	381.00	+
54	A/C CONDENSER REFRIGERANT LINE	1 S	277.00	+
55	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1 S	16.32	21.00 ✓ <i>sls.</i>
56	CHARGE AIR COOLER <i>new</i>	1 S	654.00	+
57	CHARGE AIR COOLER PRESSURE PIPE <i>new</i>	1 S	496.00	+
58	CHARGE AIR COOLER PRESSURE HOSE	1 S	413.00	+
59	RADIATOR <i>new</i>	1 S	1,013.00	+
60	READY-MIX COOLANT <i>new</i>	6 S	297.00	✓ 237.12
SUB TOTAL SPARE PARTS		:	\$ 23,309.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 8107 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE LH RH INNER } <i>Done</i>	2	\$ 51.20 64.00	☒
62	RADIATOR AIR GUIDE LH RH OUTER } <i>Done</i>	2	\$ 26.76 28.00	☒
63	RADIATOR AIR GUIDE - UPPER / LOWER <i>new</i>	2	\$ 44.00	☒
64	RADIATOR FAN RING <i>new</i>	1	\$ 292.00	☒
65	RADIATOR FAN CONTROL UNIT <i>new</i>	1	\$ 2,489.00	☒
66	INTAKE AIR DUCT - RH LOWER <i>new</i>	1	\$ 25.00	☒
67	ENGINE AIR INTAKE HOSE - CENTER <i>new</i>	1	\$ 61.00	☒
68	FRONT NO PLATE <i>But</i>	S/N	\$ 60.00	☒
69	SUNDRIES ? <i>new</i>		\$ 500.00	☒ <i>2,881</i>
TOTAL SPARE PARTS		:	\$ 44,026.00	
TOTAL LABOUR CHARGES		:	\$ 11,872.00	
GRAND TOTAL		:	\$ 55,898.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *27/12/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 08 Days. 8/8*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT