

REPAIR DETAILS

Repairer Estimates

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2022)
 Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SH6755Z/27/12/2022 15:13
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY <i>de</i>	25.00	0.00	*586.18 FL ✓
2	10		*FRT BUMPER CLIPS <i>nn</i>	25.00	0.00	*22.00 FL ✓
3	1		*FRT BUMPER LOWER GRILLE <i>7x17</i>	25.00	0.00	*193.18 FL
4	1		*FRT NUMBER PLATE <i>4 cm</i>	0.00	0.00	*50.00 F ✓
5	1		*FRT BUMPER FOG LAMP LH <i>X nn</i>	25.00	0.00	*920.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						1,771.36
- List Item Discount on L Items (S\$)						430.34
Total Parts (S\$)						1,341.02

ComfortDelGro Engineering Pte Ltd/SH6755Z/27/12/2022 15:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 400.00
2	SPRAYPAINT	New	250 300.00
3	CHECK WIRING	New	11 50.00
Gross Labour Cost (S\$)			750.00

ComfortDelGro Engineering Pte Ltd/SH6755Z/27/12/2022 15:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Passer
Hp 90010068
2 days
43
28/12/22 @ 1500
Ready after repair

456.13
50.00
11.00
600.00
1117.13
209
893.70
43-900/2 days