

(08/11/13) Wef
ASS. REC. BY: Paul

REF: CS/EA/22012909/R y3

821R

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SAA 45194
at Workshop n/s Comfort Mekan
of Loyangh
Insured: QAI
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SAA 45194 Yr Regn: 2017 JAN
Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: HYUNDAI I40 1.7 CRDI c.c. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 762896 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMPLB41UMH U098227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLACE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/12/22 D.O.I. 28/12/22

Survey held at COMFORT LOYANGH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS \$ _____

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL**EQ Insurance Company Ltd (HQ)** (CLIS)

Singapore

LKK-Rasul**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/12/2022
Vehicle Reg. No.:	SHA4519U	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	11/01/2017
Vehicle Colour:	BLUE	Chassis No:	KMHLB41UMHU098227
Engine No:	D4FDFU561955		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	7,821.40
Miscellaneous Items	0.00
Labour	3,680.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	11,501.40
+ GST 7.00% (S\$)	805.10
Nett Amount (S\$)	12,306.50

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)	Lim Tien Siong
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	ComfortDelGro Engineering Pte Ltd/SHA4519U/27/12/2022 15:16		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR RH <i>repair</i>	20.00	0.00	*2,707.70 FL
2	1		*REAR DOOR RH <i>repair</i>	20.00	0.00	*2,416.80 FL
3	1		*REAR FENDER RH <i>bt</i>	20.00	0.00	*2,171.40 FL
4	1		*REAR BUMPER <i>See</i>	20.00	0.00	*553.00 FL
5	10		*REAR BUMPER CLIPS <i>see</i>	20.00	0.00	*22.00 FL
6	1		*REAR WHEEL CAP RH <i>de</i>	20.00	0.00	*217.20 FL
7	1		*ROCKER PANEL GARNISH RH <i>de</i>	20.00	0.00	*732.80 FL
8	1		*REAR WHEEL RIM RH <i>Frqair</i>	20.00	0.00	*325.30 FL
9	1		*REAR WESTLAKE TYRE RH <i>X</i>	0.00	0.00	*216.00 F
10	1		*FRT DOOR COMFORTDELGRO RH <i>see</i>	0.00	0.00	*75.00 F
11	1		*REAR DOOR ZIG RH <i>see</i>	0.00	0.00	*80.00 F
12	1		*REAR WINDSCREEN MOULDING <i>see</i>	20.00	0.00	*51.80 FL
13	2		*REAR WINDSCREEN SEALANT <i>see</i>	0.00	0.00	*92.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	9,661.00
- List Item Discount on L Items (S\$)	1,839.60
Total Parts (S\$)	7,821.40

ComfortDelGro Engineering Pte Ltd/SHA4519U/27/12/2022 15:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Lim Tien Siong

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 1120	1200.00
2	SPRAY PAINTING	New 1250	1500.00
3	TUFF KOTE	New 60	200.00
4	TRANSFER DOORS	New X	240.00
5	WHEEL ALIGNMENT	New 60	120.00
6	R/I REAR WINDSCREEN	New 120	150.00
7	R/I REVERSE SENSORS	New 40	120.00
8	R/I UPHOLSTERY ETC	New 60	150.00
Gross Labour Cost (S\$)			3,680.00

ComfortDelGro Engineering Pte Ltd/SHA4519U/27/12/2022 15:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Passue
Hp 900100 68
8 days
43
28/12/22 @ 1510
Resurvey after repair

Need Taxi Replacement

Long TS

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9756

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 27.12.2022 15:01

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5507564

JC NO 305540937

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO: SHA4519U	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 27.12.2022 13:20
YR OF MANU 11.01.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU098227	COMPLETION DATE/TIME:

(R) (P) (O)

COUNT CARD NO.

Merimen

JOB DESCRIPTION


LS

SFL

EQ Ins - 6236M

DESCRIPTION
LUMPSUM REPAIR-SHA4519U-TP

LABOR CODE
PB



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: **SHA4519U**

LIMITS

Vehicle No.:

SHA4519U

Signature/Date

Signature/Date

Name of Service Advisor

Date

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

Vehicle Details

Vehicle No.:

SHA4519U

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Dec 2022

Vehicle Make:

HYUNDAI

Vehicle Model:

I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

D4FDFU561955

Chassis No.:

KMHLB41UMHU098227

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$20,165.00

Original Registration Date:

11 Jan 2017

First Registration Date:

11 Jan 2017

Transfer Count:

0

Actual ARF Paid:

\$20,251.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

10 Jan 2025

PARF Rebate Amount:

\$14,161.00

Intended COE Rebate Details

COE Expiry Date:

10 Jan 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$40,516.00

COE Rebate Amount:

\$10,305.00

Total Rebate Amount:

\$24,466.00