



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PD 572E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RIGHT SIDE MIRROR ASSY	CRACKED	1,140.00	1,100.00
1	RIGHT TAILLAMP	SCRATCHED	780.00	320.00
	LESS 10% DISCOUNT		-	-142.00
			1,920.00	1,278.00
	<u>SPECIAL NETT ITEMS</u>			
1	RIGHT FRONT DOOR 'EXCURSION' STICKER (SN)	NOT NECESSARY	35.00	-
			35.00	-
	<u>LABOUR</u>			
	CHECK WIRING .	NOT NECESSARY	50.00	-
	ANTI RUST PROOF.	NOT NECESSARY	50.00	-
	PANEL BEATING.		350.00	300.00
	PAINT WORK.		650.00	550.00
			1,100.00	850.00
	GRAND TOTAL		3,055.00	2,128.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/SMO22012910/Uny3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.