

SLG3990T.

TP Liberty.

Mitsubishi Attrage.

Veron.

MMBSTA13AHH 002792.

Rear Bumper	Distorted	765.10 ✓
Rear Bumper Clips.	Xec	30(SN) ✓
Rear Bumper Side Holder x 02	RT Dented	35.2 x 2 = 70.40 ✓ 35.20
Rear Bumper Reflector x 02	RT cracked	45.4 x 2 = 90.80 ✓ 45.40
Rear Bumper Chrome Moulding (Accessory)	Nec	200(SN) 100(SN) ✓
Reverse Sensor.	Damaged	280(SN) 200(SN) ✓
Rear End Panel.	Distorted	482.50 ✓
Rear End Panel Top Garnish.	Deformed	174.70 ✓
Rear End Panel Top Garnish Clips.	Nec	20(SN) ✓
Rear End Panel Air Vent.	Cracked	89.40 ✓ 335.40
Tail Lamp x 02.	RT Cracked	335.4 x 2 = 670.80 ✓
Tail Lamp Panel RH.	Dented	157.80 ✓
Bootlid	Buckled.	828.40 ✓
Bootlid Lock.	Nec	139.70 ✓
Bootlid Weatherstripe.	XHP	185.60 ✓

SLG 3990T.

Buzzer	} NP rev	91.20. ✓
Antenna Sensor.		98.40. ✓
Rear RH Fender	Buckled	832.40. ✓
Rear RH Fender Inner Trim.	turn	245.10. ✓
Rear RH Fender Inner Trim Clips.	rev	30(SN) ✓
Rear Windscreen Moulding.	} Nee	105.40 ✓
Rear Windscreen Sealant.		60(SN) ✓
Spare Tyre Panel.	Buckled.	895.60 ✓
Spare Tyre Panel Top Cover.	turn	212.40. ✓
Spare Tyre Panel Insulation Pad	rev	280 200(SN)
Rear Exhaust Pipe.	} NP rev	755.40. ✓
Rear Exhaust Pipe Mounting.		36.10. ✓
Rear Exhaust Pipe Gasket.		32.50. ✓
Front Driver Seat.	Bent	1200(SN) 800(SN)
Mitsubishi Logo.	} Nee	50.90. ✓
A Hinge Wording.		55.10. ✓
Cycle and Carriage Logo.		42.90 ✓

SLG 3990T.

Panel Beating	1800 1400
Spray Painting.	1600 1100
Wiring.	100 30
To apply tuff coat.	150 80
To remove reverse sensor.	100 50
To remove rear camera.	100 50
To remove upholstery.	150 60
To remove exhaust pipe.	150 X.
To remove rear windscreen.	180 120
To remove front driver seat.	150 80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

hist: 5353.70

Len 10%: 4818.33.

S.N: 4440

tabour: 2970

total: 9228.33.

L/S: 7.3K. 12 Days