

MS Car Auto Pte Ltd

Tel: 6385-1838 / 9725 4442 Fax: 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com / msgroupoffice@gmail.com

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

SJE : _____

Vehicle Nos : SLZ 2908 P

Date of Survey : _____

Model : HONDA VEZEL

Contacts : _____

Year : _____

**** AGREED COR and Days with SJE ****

Amount : _____

TP Liberty Veron.

Nos.	PARTS	QTY	UNIT S\$	Total S\$	REMARKS IF ANY
REAR PORTION ONLY					
1	TAILGATE <i>Dented</i>	1	\$ 1100	\$ 1100	—
2	TAILGATE MOULDING <i>new</i>	1	\$ 123.80	\$ 123.80	+
3	TAILGATE GARNISH <i>new</i>	1	\$ 395.20	\$ 395.20	+
4	TAILGATE LOGO <i>new</i>	1	\$ 32.90	\$ 32.90	+
5	TAILGATE VEZEL WORDING <i>new</i>	1	\$ 38.60	\$ 38.60	+
6	TAILGATE REFLECTOR LH <i>new</i>	1	\$ 413.90	\$ 413.90	+
7	TAILGATE REFLECTOR RH <i>new</i>	1	\$ 413.90	\$ 413.90	+
8	TAILGATE HANDLE SWITCH <i>new</i>	1	\$ 131.70	\$ 131.70	+
9	TAILGATE NO. PLATE LAMP LH <i>new</i>	1	\$ 49.90	\$ 49.90	+
10	TAILGATE NO. PLATE LAMP RH <i>new</i>	1	\$ 49.90	\$ 49.90	+
11	TAILGATE HINGE LH <i>new</i>	1	\$ 50.90	\$ 50.90	+
12	TAILGATE HINGE RH <i>new</i>	1	\$ 50.90	\$ 50.90	+
13	TAILGATE ABSORBER LH <i>new</i>	1	\$ 192.50	\$ 192.50	+
14	TAILGATE ABSORBER RH <i>new</i>	1	\$ 192.50	\$ 192.50	+
15	TAILGATE INNER BOARD <i>new</i>	1	\$ 270.30	\$ 270.30	+
16	TAILGATE LOCK <i>Dented</i>	1	\$ 216.20	\$ 216.20	—
17	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 198.90	\$ 198.90	+
18	TAILGATE STOPPER <i>new</i>	2	\$ 29.40	\$ 58.80	+
19	TAIL LAMP LH <i>new</i>	1	\$ 552.80	\$ 552.80	+
20	TAIL LAMP RH <i>new</i>	1	\$ 552.80	\$ 552.80	+
21	TAIL LAMP PANEL LH <i>new</i>	1	\$ 138.20	\$ 138.20	+
22	TAIL LAMP PANEL RH <i>new</i>	1	\$ 138.20	\$ 138.20	+
23	REAR BUMPER <i>Dented</i>	1	\$ 762.70	\$ 762.70	—
24	REAR BUMPER RETAINER LH <i>new</i>	1	\$ 16.40	\$ 16.40	—
25	REAR BUMPER RETAINER RH <i>new</i>	1	\$ 16.40	\$ 16.40	—
26	REAR BUMPER LH <i>new</i>	1	\$ 195.80	\$ 195.80	+
27	REAR BUMPER RH <i>new</i>	1	\$ 195.80	\$ 195.80	+
28	REAR END PANEL <i>Dented</i>	1	\$ 480.30	\$ 480.30	2+
29	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 102.50	\$ 102.50	2+
30	REAR END PANEL SENSOR <i>new</i>	1	\$ 121.50	\$ 121.50	+
31	REAR END PANEL SENSOR BUZZER <i>new</i>	1	\$ 98.70	\$ 98.70	+
32	REAR WELL PANEL <i>new</i>	1	\$ 858.80	\$ 858.80	+
33	REAR WELL PANEL TOP BOARD <i>new</i>	1	\$ 470.20	\$ 470.20	+
34	REAR WELL PANEL TOOL TRAY <i>cracked</i>	1	\$ 173.30	\$ 173.30	+
35	REAR WELL PANEL BATTERY <i>new</i>	1	\$ 2,309.90	\$ 2,309.90	+
36	REAR WELL PANEL LOWER COVER <i>new</i>	1	\$ 213.20	\$ 213.20	+
37	REAR WELL PANEL TOW BRACKET <i>new</i>	1	\$ 105.90	\$ 105.90	+
38	REAR CHASSIS FRAME LH <i>new</i>	1	\$ 567.80	\$ 567.80	+
39	REAR CHASSIS FRAME RH <i>new</i>	1	\$ 567.80	\$ 567.80	+
40	REAR CHASSIS TOP PANEL LH <i>new</i>	1	\$ 185.30	\$ 185.30	+
41	REAR CHASSIS TOP PANEL RH <i>new</i>	1	\$ 185.30	\$ 185.30	+
42	REAR FENDER GARNISH LH <i>new</i>	1	\$ 222.80	\$ 222.80	+
43	REAR FENDER GARNISH RH <i>new</i>	1	\$ 222.80	\$ 222.80	+
44	REAR FENDER INNER BOARD LH <i>new</i>	1	\$ 589.70	\$ 589.70	+
45	REAR FENDER INNER BOARD RH <i>new</i>	1	\$ 589.70	\$ 589.70	+
46	REAR FENDER AIR VENT LH <i>new</i>	1	\$ 33.10	\$ 33.10	+
47	REAR FENDER AIR VENT RH <i>new</i>	1	\$ 33.10	\$ 33.10	+
48	REAR FENDER SHIELD LH <i>new</i>	1	\$ 152.10	\$ 152.10	+
49	REAR FENDER SHIELD RH <i>new</i>	1	\$ 152.10	\$ 152.10	+

		Total Price	\$ 14,839.10
		Less 20%	\$ 2,967.82
		Sub Total Price	\$ 11,871.28

3105.30
 less 20%: 2484.24

Nos.	PARTS	QTY	UNIT \$	Total \$	REMARKS IF ANY
	REAR PORTION ONLY				
1	REAR NO. PLATE SET <i>new</i>	1	\$ 65.00	\$ 65.00	+
2	WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	60
3	TAILGATE GARNISH CLIPS SET <i>new</i>	1	\$ 40.00	\$ 40.00	+
4	TAILGATE INNER BOARD CLIPS SET <i>new</i>	1	\$ 60.00	\$ 60.00	30
5	TAIL LAMP CLIPS <i>new</i>	2	\$ 50.00	\$ 100.00	+
6	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 60.00	\$ 120.00	+
7	REAR BUMPER REVERSE SENSOR SET <i>new</i>	1	\$ 280.00	\$ 280.00	200
8	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00	30
9	REAR END PANEL SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	60
10	REAR END PANEL TOP GARNISH CLIPS SET <i>new</i>	1	\$ 50.00	\$ 50.00	10
11	REAR WELL PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
12	REAR FENDER INNER BOARD CLIPS SET <i>new</i>	2	\$ 60.00	\$ 120.00	+
	Total			\$ 1,235.00	

390

Nos.	Claims Details : Labour and Spray Painting	Total \$	REMARKS IF ANY
	REAR PORTION ONLY		
1	Labour to panel beat/cut/weld affected panels, realign and refit/replace necessary affected parts	\$ 1,200.00	800
2	To putty and spray paint on accident affected portion	\$ 1,200.00	600
3	To remove and transfer rear windscreen to new tailgate	\$ 180.00	120
4	To transfer components to new tailgate	\$ 120.00	80
5	To disconnect/reconnect and check for proper wiring and electrical function	\$ 100.00	30
6	To apply anti rust coating	\$ 120.00	80
7	To remove and reinstall rear compartment trims	\$ 100.00	80
8	To diagnostic reset fault code back to manufactory setting	\$ 450.00	+
9	To dismantle and replace rear bumper reverse sensor with distance test	\$ 100.00	50
10	To transfer rear camera.		50
	Total	\$ 3,570.00	

1890

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAME OF SURVEYOR :

REMARKS :

PARTS TOTAL
 LABOUR TOTAL
OVERALL TOTAL

\$13,106.28

\$3,570.00

\$16,676.28

16,893.64

Adrian Cj
 h/s 28/12/22

no of days ??

06 Days.

total: 4764.24

h/s 3.8K