

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 29 Dec 2022

Preliminary Advice

Vehicle No	: SMH161K	Accident Date	: 14/12/2022
Make	: AUDI R8	Policy No.	: DMPCSNW00128452200
Assignment Date	: 27/12/2022	Excess	: S\$5,000.00
Date of Inspection	: 28/12/2022	Est. Duration of Repair	: 6 DAYS
Inspection At	: GARAGE 13 PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	224,538.93
Revised Amount	:S\$	29,527.14
Check Items (Estimated)	:S\$	167,210.24
Total	:S\$	196,737.38
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	168,000.00
COE / PARF Rebate	:S\$	20,805.00
Salvage Value	:S\$	
Margin for Repair	:S\$	147,195.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending cost price from Repairer.
Vehicle pending for Investigation.