

(HS) HS AUTOMOTIVE SERVICES

Bik 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.
TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 53081191W

Vehicle No: PJW 886404

TP Budget Direct.
Xin Yu.

INDEPENDENT SURVEYOR

☒ DIRECT SETTLEMENT

Make/Model: BMW

CHASSIS NO: _____

Date: 28-12-22

Estimate cost of repair to the above mentioned

NO.	QTY	LIST ITEMS	MARKING	UNIT \$	AMOUNT (\$S)
1	1	REAR BUMPER <i>Del.</i>	✓		\$ 1010 ✓
2	2	REAR BUMPER REFLECTOR X2 L/R <i>Enhd</i>	✓	\$ 44	\$ 88 ✓
3	4	REAR BUMPER REVERSE SENSOR X4 <i>2 pieces dng</i>	1/2	\$ 380	\$ 1520 500
4	2	REAR BUMPER RETAINER L/R <i>Enhd</i>	✓	\$ 150	\$ 300 220
5	1	REAR BUMPER TOP BRACKET <i>Enhd</i>	✓		\$ 170 ✓
6	1	REAR BUMPER AL/PLATE <i>Enhd</i>	✓		\$ 100 60
7	1	REAR BUMPER RE-INFORCEMENT <i>Del.</i>	✓		\$ 440 ✓
8	1	REAR BUMPER CLIP <i>Alu</i> (SBT)	✓		\$ 103 50
9	1	REAR END PANEL <i>Rep</i>	✗		\$ 520 ✗
10	1	REAR END TOP GARNISH <i>Alu</i>	✗		\$ 110 ✗
11	1	REAR END PANEL TOP GARNISH CLIP <i>M</i>	✗		\$ 87 ✗
12	1	REAR END PANEL WEATHER STRIP <i>Alu</i>	✓		\$ 140 ✓
13	2	REAR TAIL LAMP L/R <i>Alu</i>	✗	\$ 395	\$ 790 ✗
14	2	REAR TAIL LAMP LOWER BRACKET L/R <i>Alu</i>	✗	\$ 46	\$ 92 ✗
15	1	REAR TAIL GATE <i>Alu</i>	✗		\$ 1580 ✗
16	1	REAR TAIL GATE LOCK <i>Alu</i>	✗		\$ 172 ✗
17	2	REAR TAIL GATE REFLECTOR LAMP L/R <i>M</i>	✗	\$ 325	\$ 650 ✗
18	1	REAR EXHAUST PIPE <i>Alu</i> <i>Rep</i>	✗		\$ 1070 ✗
19	2	REAR EXHAUST PIPE TOP MOUNTING <i>Alu</i>	✗	\$ 35	\$ 70 ✗
20					

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

EMAIL ADD:

CONTACT:



HS AUTOMOTIVE SERVICES

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 53081191W

Vehicle No:

87W 88646

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

Make/Model:

BMW

CHASSIS NO:

Date:

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

MARKING

UNIT \$

AMOUNT (\$\$)

1		DANIEL BEAT			\$ 1500
2					500
3		SPRAY PAINT			600
4					30
5		CHECK WIRING			\$ 80
6					50
7		TO INSTALL REVERSE SENSOR			\$ 120
8					120
9		TO REMOVE/REPAIR EXHAUST PIPE			\$ 240
10					40
11		RUST PROOF			\$ 100
12					
13	2	Rear NUT/PLATE KAMP. 4P	Ambed ✓	110	220.
14					120.
15					
16					
17					
18					
19					
20					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28/12/22.

04 Days

Supplementary: 120

2m 10% : 108

Total: 3858.20

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

EMAIL ADD:

CONTACT:

L/S: 3050