

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS/C7/22012920/UV43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB3070A

at Workshop m/s zoom

of _____

Insured: SLX6637E

Policy No. DMPCSNW00077822203

Claims No. SNM22D209261/C02/TOHHS


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 36k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB3070A Yr Regn: 3.103/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: maxda 2 c.c. 1498

Colour: grey A/C: Insured / Std / NI / NA

Sp. Reading: 117804 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DJ2HAA01100693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or affected

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal. _____ mm L/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/12/22 D.O.I. 28/12/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 19233

20p10k.

12/1/23 4/5 4500 informed Elin (Red 7234.19, 619)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 16/1/23-typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format: Merimen

Lump Sum / t.B.t. (\$ 4500)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	271D
Vehicle Details	
Vehicle No.:	SLB3070A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	P520336621
Chassis No.:	JM6DJ2HAA01100693
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	31 Mar 2016
First Registration Date:	31 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$6,800.00 3400
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2026
PARF Rebate Amount:	\$4,420.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$14,813.00
Total Rebate Amount:	\$19,233.00

The information contained herein is correct as at 28 Dec 2022

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

**Post an Advertisement**

Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Alfa Romeo Giulia 2.9A QuadrifoglioSingle Owner, Well Maintained,
Low Depreciation
Direct Owner StarAdSort by 20 results/page**6 vehicles**

mazda 2

Any Category

Advanced Search



Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection

mazda 2

Any

Any

2016

Any

Any

Any

Available

**Mazda 2 1.5A SP****\$47,800**

\$10,770 /yr

13-Dec-2016

1,496 cc

103,000 km

Sedan

Available

Very well maintained! High loan/bank loan schemes with competitive interest tailored to suit your needs! View to believe, pity to miss! Pl...

Posted: 25-Dec-2022

**Mazda 2 1.5A****\$46,800**

\$11,310 /yr

29-Aug-2016

1,496 cc

87,062 km

Sedan

Available

Factory fitted audio system, leather seats, electronic stability control, reverse sensor, knockdown rear seats, spacious boot, auto start/st...

Posted: 23-Dec-2022

**Mazda 2 1.5A SP****\$47,800**

\$11,590 /yr

09-Sep-2016

1,496 cc

88,000 km

Sedan

Available

Beautiful Blue, Well Maintained, Comfortable And Spacious, Accident Free, New GPS AV Screen And Reverse Cam, Dash Cam DVR, View...

Posted: 16-Dec-2022

**Mazda 2 1.5A****\$48,800**

\$11,910 /yr

29-Aug-2016

1,496 cc

Sedan

Available

Well taken care by previous careful owner! View to appreciate!

United Motoring Pte Ltd

Posted: 09-Dec-2022

PREMIUM AD

**Pro-Jex V2D Auto Pte Ltd - Specialty Workshops**

Power up for excellent performance with PRO-JEX V2D, your one-stop automobile solution provider.

More info about this shop

**Mazda 2 1.5A (OPC)****\$40,800**

\$9,520 /yr

29-Jul-2016

1,496 cc

97,000 km

Sedan

Available

OPC! Option To Convert Or Remain As OPC. Fuel Efficient And Popular Mid-size Sedan. Low Cost, Low Maintenance. Road Tax Yearly \$1...

Hui Hua Credit Pte Ltd

Posted: 06-Nov-2022

**Mazda 2 1.5A****\$44,700**

\$11,350 /yr

30-Jun-2016

1,496 cc

91,000 km

Sedan

Available

Powerful and Super Fuel Efficient! Best Handling Compact Sedan In The Segment! Trade in welcome! Loan available! Act fast and call us...

Posted: 31-Oct-2022

Save this search criteria, to get email alerts whenever a match is found.

Compare

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SLB3070A
date 28.12.22 11:01

Mazda : Mazda2 : 2014- (DJ/DL) : except Rough Road Suspension : 16" Wheel

Front : Left

Actual	Before	Specified Range
-3°56'		-1°26' 0°34'
4°25'		4°14' 6°14'
1°18'		0°00' 0°11'
19°45'		
13°49'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°51'		-1°26' 0°34'
4°49'		4°14' 6°14'
0°11'		0°00' 0°11'
13°13'		
12°22'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-3°05'		-1°30' 1°30'
-0°28'		-1°30' 1°30'
6°32'		
1°28'		0°01' 0°21'

Rear : Left

Actual	Before	Specified Range
1°42'		-2°29' -0°29'
0°01'		-0°36' 1°00'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°05'		-2°29' -0°29'
0°22'		-0°36' 1°00'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°43'		-1°50' 1°30'
0°20'		0°02' 0°46'
-0°12'		-0°48' 0°48'

TECHNEATPTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SLB 3070 A
Date: 30.12.22 18:38

Mazda : Mazda2 : 2014- (DJ/DL) : Rough Road Suspension : 16" Wheel

Front : Left

Actual	Before	Specified Range
1°32'	1°32'	-1°16' 0°44'
4°18'	4°18'	4°00' 6°00'
0°01'	0°14'	0°00' 0°11'
9°01'	9°01'	
10°33'	10°33'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°21'	-1°21'	-1°16' 0°44'
4°30'	4°31'	4°00' 6°00'
-0°04'	-0°03'	0°00' 0°11'
13°41'	13°41'	
12°20'	12°20'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
2°53'	2°53'	-1°30' 1°30'
-0°12'	-0°12'	-1°30' 1°30'
-4°40'	-4°40'	
-0°04'	0°11'	0°01' 0°21'

Rear : Left

Actual	Before	Specified Range
-2°51'	-2°51'	-2°27' -0°27'
-0°18'	-0°18'	-0°39' 0°57'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°07'	-1°07'	-2°27' -0°27'
0°38'	0°36'	-0°39' 0°57'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°44'	-0°44'	-1°30' 1°30'
0°23'	0°22'	-0°04' 0°40'
-0°25'	-0°23'	-0°48' 0°48'

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

AUTOWERKS

Insurance notify
the following:
• Damage subject to confirmation
• Third party survey is on a "no cost" basis
• The legal modification(s) is allowed
• Supplementary work(s) must be surveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer

REG NO.: SLB 3070 A
MAKE/MODEL: MAZDA 2

28 December 2022

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Front bonnet	985.80
1	Front headlamp -LH	1,417.60
1	Front headlamp lower bracket	83.80
1	Front grille chrome moulding	285.00
1	Front bumper	888.80
1	Front bumper fog lamp	200.40
1	Front bumper fog lamp cover	150.30
1	Front bumper reinforcement	448.50
1	Front bumper side retainer	80.30
1	Front fender -LH	556.90
1	Front fender inner shield	200.60
1	Front wheel rim - LH	800.30
1	Front wheel hub	400.30
1	Front wheel bearing	388.80
1	Front shock absorber	485.50
1	Front knuckle arm	800.80
1	Front lower arm	535.00
1	Front tie rod	140.40
	202	8,849.10
	Less 10%	884.91
		7,964.19

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	55.00
1	Front fender inner shield clip (1 set)	55.00
1	Front tyre	400.00
		510.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	80.00
2	To remove and refit front undercarriage.	250.00
3	To conduct wheel alignment.	180.00
4	To apply undercoating.	150.00
5	Panel beating.	1,400.00
6	To re-spray painting on the affected areas.	1,200.00
		3,260.00

GRAND TOTAL :

\$ 11,734.19