

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

27 DEC 2022

## ESTIMATE

Estimate No. : b1 64483	Page No. : 1 of 5
Date Estimated : 24/12/2022	
Prepared By : Yap Mee Key	

- ESTIMATE REPAIR FOR - Deng Le 923 Bukit Timah Road #06-06  SINGAPORE 589639	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND3456L	WBATY120909H86823	16/12/2021	X3 xDrive20i	8890

DESCRIPTION	VALUE
To replace rear bumper, carrier, tail end panel and attachments.	2125 <del>850</del> 2,125.00
To respray rear bumper and affected area	<del>986</del> 1,028.00
To carry out body cavity preservation. (Per panel).	11 X 118.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	<del>168</del> 171.00
To check electrical.	280 ? 295.00
Sundries. <i>NEE</i>	? 80.00
<b>Total Labour 1:</b>	<b>3,833.00</b>

DESCRIPTION	QTY	PRIC	VALUE
TAIL PANEL <i>XAN</i>	1	542.20	542.20
REAR BUMPER CARRIER <i>? 1/2</i>	1	776.85	800.10 776.85
REAR BUMPER BOTTOM REINFORCEMENT <i>? com</i>	1	81.50	83.95 81.50
REAR UNDERRIDE GUARD (LUXURY LINE) <i>SEA</i>	1	323.55	323.55
REAR BUMPER PANEL PRIMED (X LINE PM) <i>SEA</i>	1	1,536.45	1,536.45
REAR BUMPER CLADDING (PDC) <i>SEA</i>	1	719.00	740.50 719.00
REAR BUMPER TOWING EYE COVER <i>XAN</i>	1	48.80	48.80
<b>Total Parts :</b>			<b>4,028.35</b>

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 64483  
Date Estimated : 24/12/2022  
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND3456L	WBATY120909H86823	16/12/2021	X3 xDrive20i	8890

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&Time 12/01/23 @ 1400 Excess S\$ \_\_\_\_\_

Surveyor's Name Pam Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

*Resy before paint*



Labour 1	:	3,833.00
Parts	:	4,028.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	550.29
Grand Total	:	<u>8,411.64</u>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors

BMW Dealer



## Final Report

Estimate No. : b1 64483  
Date Estimated : 24/12/2022  
Prepared By : Yap Mee Key

Page No. :

### - ESTIMATE REPAIR FOR -

Deng Le  
923 Bukit Timah Road  
#06-06

SINGAPORE 589639

### - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SND3456L	WBATY120909H86823	16/12/2021	X3 xDrive20i	8890

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

** To replace rear bumper panel, rear carrier, rear bottom reinforcement, rear underride guard, rear cladding include carrying out necessary repairs caused by the accident	2,125.00		2,125.00
---	----------	--	----------

To respray rear bumper	986.00		986.00
------------------------	--------	--	--------

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function	168.00		168.00
--	--------	--	--------

To check electrical wiring system and lightings include resetting and checking air bags for proper function	280.00		280.00
---	--------	--	--------

Sundries	80.00		80.00
----------	-------	--	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

REAR BUMPER CARRIER	800.10	1.00	0.00	800.10
---------------------	--------	------	------	--------

REAR BUMPER BOTTOM REINFORCEMENT	83.95	1.00	0.00	83.95
----------------------------------	-------	------	------	-------

# REAR UNDERRIDE GUARD (X LINE)	254.95	1.00	0.00	254.95
---------------------------------	--------	------	------	--------

REAR BUMPER PANEL PRIMED (X LINE PM)	1,536.45	1.00	0.00	1,536.45
--------------------------------------	----------	------	------	----------

REAR BUMPER CLADDING (PDC)	740.50	1.00	0.00	740.50
----------------------------	--------	------	------	--------

### # SUPPLEMENTARY ITEMS

Total Labour :	3,639.00
----------------	----------

Total Parts :	3,415.95
---------------	----------

Total Labour & Parts (before GST) :	7,054.95
-------------------------------------	----------

Deduction for Excess :	
------------------------	--

Total Repair Costs less Excess:	7,054.95
---------------------------------	----------

GST @8%:	564.40
----------	--------

Grand Total :	7,619.35
---------------	----------

### Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

A Sime Darby Motors Company

# Performance Motors

BMW Dealer



## Supplementary

Estimate No. : b1 64483  
Date Estimated : 24/12/2022  
Prepared By : Yap Mee Key

Page No. :

### - ESTIMATE REPAIR FOR -

Deng Le  
923 Bukit Timah Road  
#06-06

SINGAPORE 589639

### - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SND3456L	WBATY120909H86823	16/12/2021	X3 xDrive20i	8890

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

** To replace rear bumper panel, rear carrier, rear bottom reinforcement, rear underride guard, rear cladding include carrying out necessary repairs caused by the accident	2,125.00		2,125.00 ✓
---	----------	--	------------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# REAR UNDERRIDE GUARD (X LINE) <i>cm</i>	254.95	1.00	0.00	254.95
---	--------	------	------	--------

### # SUPPLEMENTARY ITEMS

Total Labour :	2,125.00
Total Parts :	254.95
Total Labour & Parts (before GST) :	2,379.95

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

A Sime Darby Motors Company