



**Boxfresh Pte Ltd**

7030 Ang Mo Kio Ave 5 #06-49  
Northstar @AMK Singapore 569880  
Tel : 64585441 Fax : 64553470

Vehicle No : PC2449X

Accident date : 21/12/2023

Model No : Man

Registered owner : Singapore Ducktours Pte Ltd

A69

Date of Estimates : 17/1/23

Parts Repair and Labour ( 2 days)

- a) Repair Rear Engine Cover S\$600
- b) Sand , putty and make good surface of repaired parts
- c) Painting of affected parts S\$ 400

Subtotal : S\$ 1000

Total Charge S\$ 1000

GST 8% S\$ 80

Total Bill S\$ 1080