



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49
Northstar @AMK Singapore 569880
Tel : 64585441 Fax : 64553470

Vehicle No : PC2449X

Accident date : 21/12/2023

Model No : Man

Registered owner : Singapore Ducktours Pte Ltd

A69

Date of Estimates : 17/1/23

Parts Repair and Labour (2 days)

- | | | |
|---|---------|-----|
| a) Repair Rear Engine Cover | S\$600 | 400 |
| b) Sand , putty and make good surface of repaired parts | | |
| c) Painting of affected parts | S\$ 400 | 350 |

Subtotal : S\$ 1000

Total Charge S\$ 1000

GST 8% S\$ 80

Total Bill S\$ 1080

P/P - 750

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg