

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012931/AQP3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00010442201
Claimant Vehicle No :	SJL1096K	Insured Vehicle No :	SLQ2272L
Date of Loss:	08/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209279/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL1096K	Engine No:	K20A5823881
Make & Model:	HONDA CIVIC, 2.0 TYPE-R (M)	Chassis No:	FD21403744
Reg. Date:	14/11/2008 (Man. Year: 2008)	Odometer:	217937 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,808.08	435.44	6,372.64	93.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	200.00	2,500.00	92.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,508.08	635.44	8,872.64	93.32
Approved Total (Overridden) (\$\$)		500.00		
(\$\$)	9,508.08	500.00	9,008.08	94.74
+ GST 8.00/8.00% (\$\$)	760.65	40.00	720.65	94.74
Nett Amount (\$\$)	10,268.73	540.00	9,728.73	94.74

INSPECTION

Date of Assignment:	28/12/2022	
Date Inspected:	28/12/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL1096K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	955.10 FL	*- FL
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	80.00 FL	*- FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	36.50 FL	*- FL
4	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	36.50 FL	*- FL
5	1		*LH HEADLAMP ASSY	Not Necessary	1,187.90 FL	*- FL
6	1		*LH FRONT FENDER	Not Necessary	789.90 FL	*- FL
7	1		*LH FRONT FENDER SPLASH SHIELD	Not Necessary	110.70 FL	*- FL
8	1		*SET LH FRONT FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FL	*- FL
9	1		*LH FRONT LOWER ARM	Not Necessary	376.80 FL	*- FL
10	1		*LH FRONT WHEEL BEARING	Not Necessary	144.30 FL	*- FL
11	1		*LH FRONT WHEEL BEARING HUB	Not Necessary	211.50 FL	*- FL
12	1		*LH FRONT KNUCKLE ARM	Not Necessary	602.30 FL	*- FL
13	1		*LH FRONT KNUCKLE ARM BALL JOINT	Not Necessary	97.20 FL	*- FL
14	1		*LH FRONT TIE ROD END	Not Necessary	77.90 FL	*- FL
15	1		*LH FRONT SIDE MIRROR ASSY	Damaged	544.30 FL	*544.30 FL
16	1		*LH FRONT DOOR	Not Necessary	931.80 FL	*- FL
17	1		*LH FRONT DOOR FRAME BLACK STICKER	Not Necessary	57.40 FL	*- FL
18	1		*FRONT LH SPORT RIM	Not Necessary	1,280.00 FS	*- FS
19	1		*FRONT LH TYRE	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,070.10	544.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,262.02	108.86
Total Parts (\$\$)	6,808.08	435.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,000.00	100.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	100.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	60.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	50.00	0.00
5	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	150.00	0.00
6	REMOVE AND REPLACE LH FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	320.00	0.00
7	REMOVE AND REINSTALL LH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	120.00	0.00
Gross Labour Cost (\$\$)			2,700.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >