

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 04 Apr 2023

**Preliminary Advice**

|                    |                                                                                                             |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLQ2272L                                                                                                  |                         |              |
| TP Vehicle No      | : SJL1096K                                                                                                  | Accident Date           | : 08/12/2022 |
| Make               | : HONDA CIVIC                                                                                               | Assignment Date         | : 28/12/2022 |
| Date of Inspection | : 28/12/2022                                                                                                | Est. Duration of Repair | : 2          |
| Inspection At      | : BIFROST AUTO PTE LTD (KAKI BUKIT)<br>8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,192.58 |
| Revised Amount              | :S\$ | 635.44   |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 635.44   |
| Lump Sum Repair             | :S\$ | 500.00   |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.