BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJL1096K

Make & Model: Honda Civic Type R

Chassis number: FD21403744

Date of survey:

Name of surveyor:

| 00 | +- | 240 | |
|------|-----|-----|--|
| 1 () | nta | CIS | |
| | | | |

| No. | Description of spare parts | Qty | Ar | nount S\$ |
|-----|-------------------------------------|------|----|-----------|
| 1 | Front bumper | 1 | \$ | 955.10 |
| 2 | Front bumper clips | 1set | \$ | 80.00 |
| 3 | Front bumper RH side retainer | 1 | \$ | 36.50 |
| 4 | Front bumper LH side retainer | 1 | \$ | 36.50 |
| 5 | LH headlamp assy | 1 | \$ | 1,187.90 |
| 6 | LH front fender | 1 | \$ | 789.90 |
| 7 | LH front fender splash shield | 1 | \$ | 110.70 |
| 8 | LH front fender splash shield clips | 1set | \$ | 70.00 |
| 9 | LH front lower arm | 1 | \$ | 376.80 |
| 10 | LH front wheel bearing | 1 | \$ | 144.30 |
| 11 | LH front wheel bearing hub | 1 | \$ | 211.50 |
| 12 | LH front knuckle arm | 1 | \$ | 602.30 |
| 13 | LH front knuckle arm ball joint | 1 | \$ | 97.20 |
| 14 | LH front tie rod end | 1 | \$ | 77.90 |
| 15 | LH front side mirror assy | 1 | \$ | 544.30 |
| 16 | LH front door | 1 | \$ | 931.80 |
| 17 | LH front door frame black sticker | 1 | \$ | 57.40 |
| | | | | |
| | | | | |

\$44.35.4 \$ 6,310.10 435.4 \$ Parts less 20% \$ 1,577.53 Total \$ 4,732.58

| No. | Special Nett Items | Qty | A | mount S\$ |
|-----|--------------------|--------|----|-----------|
| 1 | Front LH sport rim | 1 | \$ | 1,280.00 |
| 2 | Front LH tyre | 1 | \$ | 480.00 |
| | | Total: | \$ | 1 760 00 |

| No. | Labour and painting | Amount S\$ |
|-----|---------------------|------------|
| | | |
| | | |

| 1 | Labour charges to remove, check, replace and reinstall | \$ 1,000.00 |
|---|--|----------------|
| | damages bodyparts. To panel beating, cut/weld and | |
| | realign all affected panels and areas | |
| 2 | Spray painting on affected areas and panels | \$ 1,000.00 |
| 3 | Check wiring and lighting system on affected areas | \$ 60.00 |
| 4 | Apply rust coating chemical on affected areas and panels | \$ 50.00 |
| 5 | Test drive and adjust wheel alignment system | \$ 150.00 |
| 6 | Remove and replace LH front undercarriage parts to assist repair | \$ 320.00 F |
| 7 | Remove and reinstall LH front door inner mechansim to new door | \$ 120.00 |
| | | |
| | Total: | \$ 2,700.00 |

Agreed Amount: ___(Part by Part / Lump sum) Working days:

Spare Parts: \$ 4,732.58 \$ 1,760.00 Special Nett: Labour: 2,700.00

Total Amount: 9,192.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ci 28/12/22 02 Pyr. tolal: 635.44. 1/5: 500.