

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : FBR2009U
VEHICLE MODEL : HONDA ADV
CHASSIS NO : MH1KF6115KK014026

TP Budget Direct.
Veron.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT WHEEL FENDER <i>Rear</i>	1	\$ 168.00	\$ 168.00	+
2	RFRONT WINDSHIELD <i>Cracked</i>	1	\$ 288.00	\$ 288.00	✓
3	FRONT WINDSHIELD BRACKET <i>New</i>	1	\$ 342.00	\$ 342.00	+
4	FRONT COWLING <i>New</i>	1	\$ 110.00	\$ 110.00	+
5	FRONT SIDE COWLING <i>Cracked</i>	2	\$ 190.00	\$ 380.00	120.380
6	FRONT COWLING LOWER GARNISH (BLACK) <i>Cr</i>	1	\$ 185.00	\$ 185.00	✓
7	HEADLAMP <i>Cracked</i>	1	\$ 755.00	\$ 755.00	✓
8	FRONT LH SIGNAL LAMP <i>New</i>	1	\$ 95.00	\$ 95.00	+
9	BALANCER LH <i>Cr</i>	1	\$ 55.00	\$ 55.00	✓
10	FRONT LH HAND LEVER <i>Cr</i>	1	\$ 48.00	\$ 48.00	✓
11	FRONT LH WING MIRROR <i>Cr</i>	1	\$ 65.00	\$ 65.00	✓
12	HANDLE BAR <i>New</i>	1	\$ 180.00	\$ 180.00	+
13	FRONT FORK ASSY <i>Best</i>	1	\$ 680.00	\$ 680.00	✓
14	FRONT FORK UNDER BRACKET <i>3 New</i>	1	\$ 220.00	\$ 220.00	✓
15	STEERING CONE & BEARING	1	\$ 120.00	\$ 120.00	✓
16	SIDE COWLING LH <i>Cracked. New</i>	1	\$ 105.00	\$ 105.00	+
17	STEP PANEL GARNISH LH <i>Cr</i>	1	\$ 370.00	\$ 370.00	✓
18	REAR LH FOOTREST <i>New</i>	1	\$ 60.00	\$ 60.00	+
19	REAR LH FOOTREST BRACKET <i>New</i>	1	\$ 120.00	\$ 120.00	+
20	ENGINE TOP COVER <i>Cr</i>	1	\$ 350.00	\$ 350.00	✓
TOTAL PRICE:				\$ 4,941.00 4696	
LESS 10%				\$ 494.10 469.60	
SUB TOTAL PRICE:				\$ 4,446.90 4226.40	

3516.
3164.40.

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT NUMBER PLATE <i>New</i>	1	\$ 15.00	\$ 15.00	✓
2	FORK OIL <i>New</i>	1	\$ 30.00	\$ 30.00	✓
3	STEP PANEL GARNISH TOP PLATE <i>New</i>	1	\$ 50.00	\$ 50.00	+
4	REAR BOX <i>Cr</i>	1	\$ 280.00	\$ 280.00	200.
5	REAR BOX BRACKET <i>New</i>	1	\$ 250.00	\$ 250.00	+
6	STICKERS <i>New</i>	1 SET	\$ 50.00	\$ 50.00	✓
TOTAL :				\$ 675.00	

295

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	200	

3	WIRING CHECK	\$ 50.00	30	
4	TO STRAIGHTEN CHASSIS BODY	\$ 250.00	+	

TOTAL: \$ 1,100.00

430.

ESTIMATE REPORT

TOTAL PARTS COST: \$ ~~5,421.90~~ 4901.40

TOTAL LABOUR COST: \$ 1,100.00

TOTAL REPAIR COST: \$ ~~6,221.90~~ 6001.40.

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 3889.40

h/s: 3.1K.

04 Days

3.1K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: