

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012935/UVP3E2**Date:** 10/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00103142200
Claimant Vehicle No :	SKC2050X	Insured Vehicle No :	GBH7043P
Date of Loss:	27/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209307/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC2050X		
Make & Model:	VOLKSWAGEN TOURAN, 1.6 CL 280 TDI EQP (A)	Engine No:	DGD064845
Reg. Date:	20/12/2017 (Man. Year: 2017)	Chassis No:	WVGZZZ1TZJW036854
Colour:	Blue	Odometer:	111709 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,256.84	4,612.54	10,644.30	69.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,120.00	2,740.00	70.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,116.84	5,732.54	13,384.30	70.01
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	19,116.84	4,500.00	14,616.84	76.46
+ GST 8.00/8.00% (S\$)	1,529.35	360.00	1,169.35	76.46
Nett Amount (S\$)	20,646.19	4,860.00	15,786.19	76.46

INSPECTION

Date of Assignment:	28/12/2022	
Date Inspected:	28/12/2022	Inspected At: Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jan 2023)	
Parts:	N/A	VOLKSWAGEN TOURAN 1.6 CL 280 TDI EQP (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC2050X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,477.80 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINERS	Not Necessary	98.60 FL	*- FL
3	1		*REAR BUMPER ATTACHEMENT RETAINERS	Not Necessary	92.30 FL	*- FL
4	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
5	1		*TAILLAMPS	Not Necessary	398.60 FL	*- FL
6	1		*TAILLAMPS INNER SEALER	Not Necessary	38.00 FL	*- FL
7	1		*SET TAILLAMP CLIPS	Not Necessary	30.00 FL	*- FL
8	1		*REAR FENDER LH	Repair	1,708.90 FL	*- FL
9	1		*REAR FENDER GLASS WITH MOULDING RH	Not Necessary	426.10 FL	*- FL
10	1		*REAR FENDER GLASS INNER SEAL RH	Not Necessary	50.00 FL	*- FL
11	1		*REAR FENDER INNER TRIM	Not Necessary	425.80 FL	*- FL
12	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FL	*- FL
13	1		*REAR FENDER INNER SHIELD LH	Not Necessary	182.30 FL	*- FL
14	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
15	1		*REAR DOOR LH	Badly Dented	2,023.60 FL	*2,023.60 FL
16	1		*REAR DOOR GLASS LH	Broken	498.50 FL	*498.50 FL
17	1		*REAR DOOR OUTER MOULDING LH	Bent	179.50 FL	*179.50 FL
18	1		*REAR DOOR INNER LOCK LH	Damaged	385.90 FL	*385.90 FL
19	1		*REAR DOOR LOCK CATCH LH	Not Necessary	45.80 FL	*- FL
20	1		*REAR DOOR OUTER HANDLE LH	Cut	298.70 FL	*298.70 FL
21	1		*REAR DOOR PILLAR GARNISH LH (GLOSS BLACK)	Necessary	129.80 FL	*129.80 FL
22	1		*REAR DOOR WEATHERSTRIP LH (DOOR)	Necessary	198.50 FL	*198.50 FL
23	1		*REAR DOOR WEATHERSTRIP LH (FRAME)	Not Necessary	205.60 FL	*- FL
24	1		*REAR DOOR GLASS REGULATOR GEAR	Bent	635.90 FL	*392.00 FL
25	1		*REAR DOOR GLASS REGULATOR MOTOR	Not Necessary	408.70 FL	*- FL
26	2		*REAR DOOR HINGES	Not Necessary	159.60 FL	*- FL
27	2		*REAR DOOR STOPPER	Not Necessary	70.00 FL	*- FL
28	1		*REAR DOOR CHECKER	Not Necessary	58.30 FL	*- FL
29	1		*REAR DOOR INNER TRIM	Deformed / Torn	1,300.21 FL	*845.21 FL
30	1		*SET REAR DOOR INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
31	1		*REAR DOOR SPEAKER	Not Necessary	254.60 FL	*- FL
32	1		*FRONT DOOR LH	Not Necessary	2,013.90 FL	*- FL
33	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	285.60 FL	*- FL
34	1		*FRONT DOOR CENTRE PILLAR	Not Necessary	985.20 FL	*- FL
35	1		*SIDE ROCKER PANEL LH	Not Necessary	798.50 FL	*- FL
36	1		*REAR FENDER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
37	1		*BODY PANEL JOINT SEALANT	Not Necessary	120.00 FS	*- FS
38	1		*REAR DOOR GLASS SOLAR FILM	Necessary	480.00 FS	*120.00 FS
39	1		*REAR DOOR QUARTER GLASS WITH WEATHERSTRIP	Not Necessary	223.90 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,878.71 5,111.71

- List Item Discount on L Items 10.00/10.00% (\$\$) 1,621.87 499.17

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	15,256.84
						4,612.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	500.00
2	SPRAY PAINTING	New	1,600.00	450.00
3	CHECK WIRING ON TAILLAMP	New	80.00	0.00
4	ANTI RUST	New	150.00	30.00
5	REMOVE AND INSTALL REAR QUARTER GLASS	New	100.00	0.00
6	REMOVE AND INSTALL REAR DOOR PARTS & MECHANISM	New	150.00	60.00
7	REMOVE AND INSTALL INTERIOR UPHOLSTERY	New	180.00	80.00
Gross Labour Cost (S\$)			3,860.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >