



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 1632R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AUDI REAR BOOT LID LAMP RH (OUTER) A6	CRACKED	600.00	600.00
1	AUDI REAR BOOT LID LAMP RH (INNER) A6	CRACKED	600.00	600.00
1	AUDI REAR BUMPER ASSEMBLY A6	BUCKLED/CUT	2,100.00	2,054.80
1	AUDI REAR BUMPER LOWER DIFFUSER A6	CUT	422.00	389.00
1	AUDI REAR BUMPER SIDE BRACKET RH A6	SERVICEABLE	70.00	-
1	AUDI BOOT LID EMBLEM (2.0T)	NECESSARY	110.00	110.00
1	AUDI REAR BUMPER TOW COVER A6	SERVICEABLE	80.00	-
1	AUDI REAR BUMPER REINFORCEMENT BAR A6	TO REPAIR SEE LABOUR	1,180.00	-
1	AUDI REAR BUMPER PARKING SENSOR A6	SERVICEABLE	280.00	-
	LESS 5% DISCOUNT		-	-187.69
			5,442.00	3,566.11
	<u>LABOUR</u>			
	TO REMOVE/INSTALL & REPLACEMENT OF REAR BUMPER, REAR BUMPER LOWER DIFFUSER , REAR BUMPER SIDE BRACKET, REAR BUMPER REINFORCEMENT BAR , TO TRANSFER BUMPER COMPONENTS PARTS. INCLUSIVE OF THE REPAIR OF AUDI REAR BUMPER REINFORCEMENT BAR A6.		800.00	300.00
	TO PUTTY , SPRAY PAINTING REAR BUMPER & BOOT LID ASSEMBLY.		800.00	440.00
	TO CHECK WIRING INCLUDING ELECTRICAL FOR FAULT CODE & RESET.		120.00	60.00
			1,720.00	800.00
	GRAND TOTAL		7,162.00	4,366.11
	RECOMMENDED COST OF REPAIRS			4,366.11

Report Ref No. CS/FCI22012936/Kny3m4

MARKET VALUE: \$42,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$28,764.00=NETT VALUE: \$13,236.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.