



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22012936/Kny3m4 Date: 17/01/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 5749B	Veh. Inspected	SGD 1632R
Policy No.		Coverage (\$)	0.00
Claim No.	D23000023MFCV	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	28/12/2022
2. Vehicle Particulars & Condition			
Make & Model	AUDI A6 (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WAUZZZ4G8EN025289	Colour	METALLIC PEARL WHITE
Odometer	119086 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	GOODYEAR	5 mm
L/H Front Tyre	225/55 R17	GOODYEAR	5 mm
R/H Rear Tyre	225/55 R17	GOODYEAR	5 mm
L/H Rear Tyre	225/55 R17	GOODYEAR	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/12/2022	Inspection Date	29/12/2022
Survey held at	MOTOR EDGEVANTAGE PTE LTD 160 SIN MING DRIVE #03-02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	