

## MOTOR **EDGE**VANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 2 8 657 201534758N +65 6453 7683 Significant Company of the Company of

To:

5

Mr Charles Loh

SGD1632R, AUDI, A6 2.0 TFSI MU

1003 Bukit Timah Road

The Sterling Singapore 596289

Attn: Charles Loh (91058999)

NOT Norhorisal Burny 84 painy Date: 27/12/2022 13:00

3day, Time out:

8 4366.11

		0 / 300.//						
T	Job Description	Operation	Our	antity		иом	Unit Price	Amt
	Essential Works	- porture on	Que	incity		ООМ	Unit Price	Amt
	Audi rear boot lid lamp RH (outer) A6		cm	1.00		PCS	600.00	500.00
	Audi rear boot lid lamp RH (inner) A6			1.00			600.00	600.00
	Audi rear bumper assembly A6 2059.	80 21	6-			PCS	600.00	600.00
;	Audi rear bumper lower diffuser A6 36			1.00		PCS	2,100.00	2,100.00
		,		1.00		PCS	422.00	422.00
	Audi rear bumper side bracket RH A6		m	1.00		PCS	70.00	70.00
	Audi boot lid emblem (2.0T)		na	1.00		PCS	110.00	110.00
	Audi rear bumper tow cover A6		Pm	1.00		PCS	80.00	80.00
	Audi rear bumper reinforcement bar A6	5%		1.00	R	PCS	1,180.00	1,180.00
	Audi rear bumper parking sensor A6			1.00		PCS	280.00	h 280.00
-	To remove/install & replacement of rear bumper, rear bumper lower diffuser , rear bumper side backet, rear bumper reinforcement bar , To ransfer bumper components parts			1.00			800.00	800.00
T	o putty , spray painting rear bumper boot lid assembly			1.00			800.00	800.00
Γα a	check wiring including electrical for ult code & reset			1.00			120.00	120.00

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal GST 7.0% 7,162.00 501.34

Total 7,663.34