



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Wong Kah Heng (wang Jiaheng)	Cust No/Name LCV15621/WONG KAH HENG (WANG JIAHENG)
BLK 898A TAMPINES ST 81	Reg No/Reg Date SLM9681P / 19/04/201
#05-770	Date In/Mileage 27/12/2022/ 66695
SINGAPORE 521898	Chassis No KNAFZ411MH5707943
Contact No Mobile: 91800489	Engine No G4FGGH651993
13/01/	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	13/01/2023/ 17:16	LER	972 / Mars Ler	15581			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT SUPPLEMENTARY LABOUR A 10028901 TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE								280.00

Estimate

Confirm &amp; accepted by

8% GST on	Nett	280.00	280.00
			22.40
	<b>Total Payable</b>		<b>302.40</b>

*Supplementary*  
 \_\_\_\_\_  
 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Wong Kah Heng (wang Jiaheng)	Cust No/Name	LCV15621/WONG KAH HENG (WANG JIAHENG)
BLK 898A TAMPINES ST 81 #05-770 SINGAPORE 521898	Reg No/Reg Date	SLM9681P / 19/04/201
Contact No Mobile: 91800489 13/01/	Date In/Mileage	27/12/2022/ 66695
	Chassis No	KNAFZ411MH5707943
	Engine No	G4FGGH651993
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK


Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	16/01/2023/ 19:03	LER	972 / Mars Ler	15581			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT ACCIDENT ON 26/12/2022 ALONG TAMPINES STREET 81 OPEN CARPARK T51 OWNER CLAIMING THIRD PARTY LOSS OF USE TP # SLA7462G TP INS: SOMPO								
M SUNDRY TO APPLY SEALANT KIT ON NEW PANEL								160.00
M SUNDRY TO APPLY ANTI-CORROSION ON ACCIDENT AFFECTED AREAS								100.00
M SUNDRY SEALANT KIT ON REAR WINDSCREEN GLASS								80.00
E PNT88000 TO INSTALL RIKECOOL SOLAR FILM ON REAR WINDSCREEN GLASS								280.00
E PNT88000 TO REMOVE AND REPLACE REAR WINDSCREEN GLASS								320.00
E PNT88000 TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY FACILITATE RENEW RHR OTR QTR PNL								640.00
E PNT88000 TO TRANSFER RHR DOOR COMPONENT & MECHANISM PARTS								320.00
E PNT88000 TO REPLACE RH SIDE AND REAR BODY KIT								320.00
E PNT88000 TO REPLACE RHR DOOR PANEL,ETC -TO REPAIR REAR BUMPER -TO CUT & REWELD RHR OTR QTR PANEL STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS								2880.00
E PNT98000 SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS								2200.00
B WHEELALIGNMENT120L To Conduct Computerize Full Wheel Alignment								180.00
E PNT88000 TO REPLACE RHR WHEEL ASSY								50.00

Confirm &amp; accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Wong Kah Heng (wang Jiaheng)	Cust No/Name	LCV15621/WONG KAH HENG (WANG JIAHENG)
BLK 898A TAMPINES ST 81	Reg No/Reg Date	SLM9681P / 19/04/201
#05-770	Date In/Mileage	27/12/2022/ 66695
SINGAPORE 521898	Chassis No	KNAFZ411MH5707943
Contact No Mobile: 91800489	Engine No	G4FGGH651993
13/01/	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	16/01/2023/ 19:03	LER	972 / Mars Ler	15581			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
-INCLUSIVE WHEEL BALANCING								
M SUNDRY								20.00
SUNDRIES								
A 10028901								280.00
TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE								
X	PANEL ASSY-REAR DOOR,RH				1.00	1183.00	00.00	1183.00
X	W/STRIP ASSY-RR DR BELT O/S RH				1.00	89.00	00.00	89.00
X	BLACK TAPE-RR DR FRAME UPR,RH				1.00	9.00	00.00	9.00
X	TAPE-RR DR FRAME BLACK RR,RH				1.00	7.00	00.00	7.00
X	PANEL ASSY-QUARTER OUTER,RH				1.00	1213.00	00.00	1213.00
X	FILM-ANTI CHIPPG RH				1.00	29.00	00.00	29.00
X	BODY KIT				1.00	1800.00	00.00	1800.00
X	GLASS ASSY-REAR WINDOW				1.00	465.00	00.00	465.00
X	MOULDING-REAR WINDOW GLASS				1.00	24.00	00.00	24.00
X	CLIP				10.00	2.00	00.00	20.00
X	BRACKET-RR BUMPER SIDE MTG,RH				1.00	29.00	00.00	29.00
X	WHEEL ASSY-ALUMINIUM				1.00	1450.00	00.00	1450.00

Confirm &amp; accepted by

	Nett	14,148.00
8% GST on	14148.00	1131.84
<b>Total Payable</b>		<b>15,279.84</b>

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.