



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Wong Kah Heng (wang Jiaheng)	Cust No/Name LCV15621/WONG KAH HENG (WANG JIAHENG)
BLK 898A TAMPINES ST 81	Reg No/Reg Date SLM9681P / 19/04/201
#05-770	Date In/Mileage 27/12/2022/ 66695
SINGAPORE 521898	Chassis No KNAFZ411MH5707943
Contact No Mobile: 91800489	Engine No G4FGGH651993
13/01/	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	13/01/2023/ 17:16	LER	972 / Mars Ler	15581

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT SUPPLEMENTARY LABOUR A 10028901 TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE				A 280.00

Estimate

Confirm & accepted by			
		8% GST on	280.00
		Nett	280.00
		Total Payable	302.40
 Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.