



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Wong Kah Heng (wang Jiaheng) BLK 898A TAMPINES ST 81 #05-770 SINGAPORE 521898 Contact No Mobile: 91800489	Cust No/Name LCV15621/WONG KAH HENG (WANG JIAHENG) Reg No/Reg Date SLM9681P / 19/04/2017 Date In/Mileage 27/12/2022/ 66695 Chassis No KNAFZ411MH5707943 Engine No G4FGGH651993 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	27/12/2022/ 17:57	LER	972 / Mars Ler	15581

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT ACCIDENT ON 26/12/2022 ALONG TAMPINES STREET 81 OPEN CARPARK T51 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SLA7462G TP INS: SOMPO				
M SUNDRY TO APPLY SEALANT KIT ON NEW PANEL				160 320.00
M SUNDRY TO APPLY ANTI-CORROSION ON ACCIDENT AFFECTED AREAS				1 200.00
M SUNDRY SEALANT KIT ON REAR WINDSCREEN GLASS				✓ 80.00
E PNT88000 TO INSTALL RIKECOOL SOLAR FILM ON REAR WINDSCREEN GLASS				✓ 280.00
E PNT88000 TO REMOVE AND REPLACE REAR WINDSCREEN GLASS				✓ 320.00
E PNT88000 TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY FACILITATE RENEW RHR OTR QTR PNL				640 1280.00
E PNT88000 TO TRANSFER RHR DOOR COMPONENT & MECHANISM PARTS				320 640.00
E PNT88000 TO REPLACE RH SIDE AND REAR BODY KIT				320 640.00
E PNT88000 TO REPLACE RHR DOOR PANEL,RR BUMPER,ETC -TO CUT & REWELD RHR OTR QTR PANEL STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS				2880 3840.00
E PNT98000 SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS				220 3300.00
B WHEELALIGNMENT120L To Conduct Computerize Full Wheel Alignment				✓ 180.00
E PNT88000 TO REPLACE RHR WHEEL ASSY -INCLUSIVE WHEEL BALANCING				✓ 50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Wong Kah Heng (wang Jiaheng) BLK 898A TAMPINES ST 81 #05-770 SINGAPORE 521898 Contact No Mobile: 91800489	Cust No/Name LCV15621/WONG KAH HENG (WANG JIAHENG) Reg No/Reg Date SLM9681P / 19/04/2017 Date In/Mileage 27/12/2022/ 66695 Chassis No KNAFZ411MH5707943 Engine No G4FGGH651993 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTPO0080	Cash	27/12/2022/ 17:57	LER	972 / Mars Ler	15581

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY SUNDRIES				20 50.00
M PANEL ASSY-REAR DOOR,RH <i>Dented</i>	1.00	1183.00	00.00	✓ 1183.00
M W/STRIP ASSY-RR DR BELT O/S RH <i>new</i>	1.00	89.00	00.00	✓ 89.00
M BLACK TAPE-RR DR FRAME UPR,RH <i>new</i>	1.00	9.00	00.00	✓ 9.00
M TAPE-RR DR FRAME BLACK RR,RH <i>new</i>	1.00	7.00	00.00	✓ 7.00
M PANEL ASSY-QUARTER OUTER,RH <i>Dented.</i>	1.00	1213.00	00.00	✓ 1213.00
M FILM-ANTI CHIPPG RH <i>new</i>	1.00	29.00	00.00	✓ 29.00
M BODY KIT <i>Dehorned</i>	1.00	1800.00	00.00	✓ 1800.00
M GLASS ASSY-REAR WINDOW <i>new</i>	1.00	465.00	00.00	✓ 465.00
M MOULDING-REAR WINDOW GLASS <i>new</i>	1.00	24.00	00.00	✓ 24.00
M COVER-RR BUMPER <i>Repr</i>	1.00	688.00	00.00	+ 688.00
M CLIP <i>new</i>	10.00	2.00	00.00	✓ 20.00
M BRACKET-RR BUMPER SIDE MTG,LH <i>new</i>	1.00	29.00	00.00	+ 29.00
M BRACKET-RR BUMPER SIDE MTG,RH <i>new</i>	1.00	29.00	00.00	✓ 29.00
M WHEEL ASSY-ALUMINIUM <i>at</i>	1.00	1450.00	00.00	✓ 1450.00

SURVEYOR NAME: Adrian Li
 SURVEYOR SIGNATURE: [Signature]
 DATE: 29/12/22
 REMARKS: HE Authorised, 08 Days.

Confirm & accepted by	LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company 	Nett	18,215.00
Authorized signatory and company stamp		7% GST on	1275.05
		Total Payable	19,490.05

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.