

FBT1316D. 2021 Nov
Honda ADV 179cc
MH1KF6110MK040018.

TP111
Xiao Chen.

Front Number Plate Sticker.	total	15(SN)	✓
Front Windshield.	crackd	288	✓
Front Windshield Bracket.	crackd	342	✓
Front Centre Cowling.	Repair	110.	X
Front Cowling Side x 02.	LH crackd	190 x 2 = 380	190
Headlamp Assy.	crackd	755	✓
Front wheel Fender.	Repair	168.	X
Front Fork Assy.	Bent	680.	✓
Front Fork Underbracket.	crackd	220	✓
Steering Cone and Bearing.	MR	120	✓
Front Fork Oil.	new	30(SN)	✓

FBT 1316D.

Balancer LH.	lt	55	/
Front Lever LH.	lt	48	/
Front LH Wing Mirror.	NP m	85	X
Front LH Signal Lamp.	cut	95	/
Front LH Crash Bar.	cut	245	/
Rear LH Footrest.	NP New	60.	X.
Rear Engine Cover (Black)	NP New	210.	X
Rear Engine Cover (Silver).	lt	168.	✓
Rear Engine Top Cover.	lt	350	/
Side Cowling LH.	RHS	125	X
Rear Seat Handle.	LH lt	155	/
Rear Container.	NP new	280(SN)	X
Rear Container Bracket.	NP m	250(SN)	X
Stickers.	New	50 (SN)	/

FBT 1316D.

Labour.

~~400~~ 200

~~400~~ 200

Spray Painting

430

~~50~~ 30

Wiring.

To repair and straighten chassis member. 200. +

List: 3711

Labour: 430

Item 10%: 3339.90

total: 3864.90

S.N: 95

1/5: 3K.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: