

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts E	n Autom	obile CS3/G	RB22010810
	INDIA INTERNATIO		Ref:	000/000000	10010/0	
	64 CECIL STREET #05-02 IOB BUILD	- ING SINGAPORE 049711		Date:	3 4/40/2022	27/12/2022
				Code:	GRB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLS 5273D	Veh. Inspected	i	GBE 4050D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	MELVINIYE CARINE KEK	Assign Date		34/49/2022	27/12/2022
2.		Vehicle Partic	ulars & Conditi	on		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.			ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description	on of Damages			
5.	General Information					
	Accident Date	26/10/2022	Inspection Dat		31/10/2022	
	Survey held at	3020A UBI ROAD 1, #01-33, SIN		•		
	Repairer EVOLUTION96 AUTO PTE. LTD.					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					