



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref: CS/ASM22012945/Kvp3e2

8 SHENTON WAY #24-01

Date: 17/01/2023

AXA TOWERSINGAPORE 068811

ATTN: TEO KITTY

Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 8363A	Veh. Inspected	SKF 6060A
Policy No.	GA426743	Coverage (\$)	0.00
Claim No.	S2M04H68	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	28/12/2022

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJGK85GG069573	Colour	METALLIC BLUE
Odometer	52226 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	8 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	8 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	8 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/12/2022	Inspection Date	05/01/2023
Survey held at	RIVERVIEW AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #04-07 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------