



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM22012945/Kvp3e2 Date: 17/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLK 8363A	Veh. Inspected	SKF 6060A
	Policy No.	GA426743	Coverage (\$)	0.00
	Claim No.	S2M04H68	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	28/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JF1SJGK85GG069573	Colour	METALLIC BLUE
	Odometer	52226 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	BRIDGESTONE	8 mm
	L/H Front Tyre	225/55 R18	BRIDGESTONE	8 mm
	R/H Rear Tyre	225/55 R18	BRIDGESTONE	8 mm
	L/H Rear Tyre	225/55 R18	BRIDGESTONE	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/12/2022	Inspection Date	05/01/2023
	Survey held at	RIVERVIEW AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #04-07 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	