

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPPOINT

SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Not Wharrah
 1/1/2018
 Lump Sum Repair
 20%
 5 days

SKF6060A
Parts

Subaru forester 2.0

List Price

Tailgate	R 1072.30 ✓
Tailgate Subaru Logo	R 78 ✓
Tailgate Subaru emblem	R 68 ✓
Tailgate AWD emblem	R 45 ✓
Tailgate forester emblem	R 70 ✓
Tailgate inner lock	R 322.80 X
Tailgate inner trim board	R 560.30 X
Tailgate shock absorbers x 2pc @ 275.40 x 2pc	R 550.80 X
Tailgate wiper motor	R 525 X
Tailgate windscreen glass moulding	R 121.50 ✓
Rear Bumper	R 740.30 ✓
Rear Bumper towing cover	R 40.70 ✓
Rear end panel top garnish	R 149.60 X
tailgate Boot weatherstrip	R 156.70 X
end panel lock catch	R 55 X
Rear Bumper reinforcement	R 499.60 X
Rear Bumper sponge	R 520.80 X
Rear end panel	R 520.80 X
tailgate antenna Key	R 520.80 X

special nett items

Rear Bumper clips (1set)
 Reverse parking sensors (1set)
 tailgate Reverse camera
 Tailgate windscreen sealant
 Rear end panel sealant

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

nett Price \$

R 40 ✓

R 250 X

R 450 X

R 80 Part

R 80 Part

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair
Less 20%

SKF6060A

Subaru forester 2.0

Labour charges

- 1) To Renew damaged parts and Repair the Accident Area. 600
\$1000
- 2) To Remove and Refit tailgate windscreen glass 120
\$200
- 3) To assemble Reverse camera and Reverse parking sensors.
To check for proper functions. 50
\$100
- 4) To spray paint Tailgate, Rear Bumper, rear end panel
and spare tyre panel 600
\$1500
- 5) To carry out anti-rust treatment at the accident area 80
\$150

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/12/2022 14:45 (SGT)
Reported by	Both
Date of Accident	25/12/2022 17:50 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE /EUNOS EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF6060A
INSURED/POLICYHOLDER	
Is company?	No
Name of Registered Owner	SUFFIAN BIN AMIN
NRIC No	S8238511H
Email Address	SUFFIANAMIN82@GMAIL.COM
Mobile Phone No	(Phone) +65-98311069
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Subaru
Model	Forester
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	AIS/2022/0000393/000058

DRIVER

Name of Driver	SUFFIAN BIN AMIN
NRIC No	S8238511H
Date Of Birth	05/11/1982
Occupation	Indoor

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, SR273511 H SUFFRAN DAN AMIN, am writing this statement to state the facts of a vehicle incident involving my personal vehicle, SKF6060A, a Subaru Forester, blue in colour and another private vehicle, a Renault, SLK8363A. This event happened on Sunday, 25 December 2022 at around 1750 hrs I was exiting PIE/TUNAS via Funos Exit, as I was filling into 5th Funos, SLK8363A bumped the rear of my vehicle I subsequently proceeded to drive forward so as to not obstruct traffic, activate my hazard lights then proceeded to alight and assess the damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)

Reporting Centre Person's Signature
Name