

VH L250

Bee Ark

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SNB 694X**

Made : Toyota

Model : Corolla Hybrid

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper / BR	1	\$ 451.60	\$ 451.60
2	Rear Bumper Side Retainer RH (Long) X	1	\$ 110.50	\$ 110.50
3	Rear Bumper Side Retainer LH (Long) X	1	\$ 110.50	\$ 110.50
4	Rear Bumper Side Retainer RH (Short) X	1	\$ 61.00	\$ 61.00
5	Rear Bumper Side Retainer LH (Short) X	1	\$ 61.00	\$ 61.00
6	Rear Bumper Reflector RH X	1	\$ 60.40	\$ 60.40
7	Rear Bumper Reflector LH X	1	\$ 60.40	\$ 60.40
8	Rear Bumper Centre Lower Garnish / AT	1	\$ 115.60	\$ 115.60
9	Rear Bumper Arm RH X	1	\$ 68.20	\$ 68.20
10	Rear Bumper Arm LH X	1	\$ 68.20	\$ 68.20
11	Rear Bumper Reinforcement X	1	\$ 399.50	\$ 399.50
12	Rear Bumper Reverse Sensor / Coat	2	\$ 151.60	\$ 303.20
13	Rear End Panel / BUL	1	\$ 685.80	\$ 685.80
14	Rear End Panel Top Garnish / RL	1	\$ 241.90	\$ 241.90
15	Electrical Antenna / BR	1	\$ 194.20	\$ 194.20
16	Rear Spare Tyre Panel X	1	\$ 859.00	\$ 859.00
17	Rear Spare Tyre Panel Top Board X	1	\$ 282.80	\$ 282.80
18	Rear Taillamp Assembly RH / BR	1	\$ 386.40	\$ 386.40
19	Rear Taillamp Assembly LH / BR	1	\$ 386.40	\$ 386.40
20	Rear Taillamp Panel RH X	1	\$ 112.30	\$ 112.30
21	Rear Taillamp Panel LH X	1	\$ 112.30	\$ 112.30
22	Rear Bootlid / BT	1	\$ 880.80	\$ 880.80
23	Rear Bootlid Weatherstrip / BT	1	\$ 175.80	\$ 175.80
24	Rear Bootlid Top Lock / BT	1	\$ 399.50	\$ 399.50
25	Rear Bootlid Lock Striker X	1	\$ 15.30	\$ 15.30
26	Rear Bootlid Hinge RH X	1	\$ 69.90	\$ 69.90
27	Rear Bootlid Hinge LH X	1	\$ 69.90	\$ 69.90
28	Rear Bootlid Emblem /	1	\$ 63.40	\$ 63.40
29	Rear Bootlid "Corolla" Emblem /	1	\$ 54.60	\$ 54.60
30	Rear Bootlid "Hybrid" Emblem /	1	\$ 63.40	\$ 63.40
31	Rear Bootlid Outer Garnish X	1	\$ 243.70	\$ 243.70
32	Rear Bootlid Reflector Lamp RH X	1	\$ 210.80	\$ 210.80
33	Rear Bootlid Reflector Lamp LH X	1	\$ 210.80	\$ 210.80

34	Rear Fender LH	X	1	\$	1,182.40	\$	1,182.40
35	Rear Fender Inner Shield LH	X	1	\$	110.45	\$	110.45
36	Rear Fender Inner Trim LH	X	1	\$	361.60	\$	361.60
37	Rear Fender Air Vent LH	X	1	\$	138.00	\$	138.00
38	Rear Fender RH	X	1	\$	1,182.40	\$	1,182.40
39	Rear Fender Inner Shield RH	X	1	\$	110.45	\$	110.45
40	Rear Fender Inner Trim RH	X	1	\$	361.60	\$	361.60
41	Rear Fender Air Vent RH	X	1	\$	138.00	\$	138.00
42	Rear Windscreen Glass Outer Moulding	X	1	\$	123.30	\$	123.30
Parts Sub Total :						\$	11,297.30
25% Discount						\$	2,824.33
PARTS TOTAL :						\$	8,472.98

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 50.00
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ 50.00
4	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 50.00
5	Rear Fender Inner Shield Clips - Set	1	\$ 40.00	\$ 40.00
6	Rear Fender Inner Trim Clips - Set	1	\$ 80.00	\$ 80.00
7	Rear Bootlid Inner Trim Clips - Set	1	\$ 50.00	\$ 50.00
8	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ 150.00
9	Rear Bootlid Sealant	1	\$ 150.00	\$ 150.00
10	Rear End Panel Sealant	1	\$ 150.00	\$ 150.00
11	Rear Spare Tyre Panel Sealant	1	\$ 150.00	\$ 150.00
12	Rear Fender LH Sealant	1	\$ 150.00	\$ 150.00
13	Rear Fender RH Sealant	1	\$ 150.00	\$ 150.00
14	Rear Reverse Camera	1	\$ 550.00	\$ 550.00
SPECIAL NETT TOTAL :				\$ 1,820.00

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 2,400.00
2	To Spray Paint Affected Areas	\$ 1,800.00
3	Wiring & Bulb Check	\$ 100.00
4	To Remove & Refix Rear Windscreen Glass	\$ 150.00
5	To Transfer Rear Bootlid Mechanism	\$ 150.00
6	To Remove & Refix Rear Reverse Camera	\$ 150.00
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00
8	To Remove & Refix Rear Exhaust Pipe	\$ 150.00
9	To Remove & Refix Fuel Tank	\$ 200.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00
11	To apply anti rust on affected parts	\$ 150.00
12	To Conduct Water Leak Test	\$ 100.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00
LABOUR TOTAL :		\$ 6,100.00

PARTS TOTAL :	\$	8,472.98
SPECIAL NETT TOTAL :	\$	1,820.00
LABOUR TOTAL :	\$	6,100.00
GRAND TOTAL :	\$	<u>16,392.98</u>

Eric Qip
 29/12/22
 Lump Sum Repir
 5 Days.