



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303900

INV Date 19/06/2023

Reference CC4/LPC22012956/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLD 9905S
Insured Veh. YN 6738X
Claim No. 22/22/23/VC06/026777
Policy No. Z22VC06113870
Accident Date 28/12/2022
Inspection Date 29/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22012956/Rpa3q2 Date: 19/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 6738X	Veh. Inspected	SLD 9905S	
Policy No.	Z22VC06113870	Coverage (\$)	0.00	
Claim No.	22/22/23/VC06/026777	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	29/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER DISCOVERY SPORT 2.0 SI4	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SALCA2AG2GH564495	Colour	WHITE	
Odometer	119395 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	PIRELLI	6 mm	
L/H Front Tyre	235/55 R19	PIRELLI	6 mm	
R/H Rear Tyre	235/55 R19	PIRELLI	6 mm	
L/H Rear Tyre	235/55 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2022	Inspection Date	29/12/2022	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 9905S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR -REAR VIEW (SN)	BROKEN	1,007.50	906.75
1	COVER -MIRROR HOUSI (SN)	MISSING	229.20	206.28
1	LAMP -EXTERIOR MIRR (SN)	CRACKED	214.10	192.69
1	MIRROR MOTOR LH MEMO (SN)	CRACKED	349.80	314.82
1	GLASS -REAR VIEW OU (SN)	BROKEN	317.20	285.48
1	LAMP -EXTERIOR MIRR (SN)	CRACKED	220.60	198.54
1	MOULDING -DOOR WIND (SN)	NOT NECESSARY	355.90	-
1	FINISHER -'A' PILLA (SN)	NOT NECESSARY	231.00	-
			2,925.30	2,104.56
	<u>LABOUR</u>			
	TO REPLACE SIDE MIRROR ASSY LH ,FRT WINDSCREEN MLDG LH .		1,500.00	1,300.00
	TO SPRAY RH SIDE MIRROR COVER ,RH A PILLAR ,RHF DOOR .		2,200.00	1,700.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODUELS.		621.00	621.00
			4,321.00	3,621.00
	GRAND TOTAL		7,246.30	5,725.56
RECOMMENDED COST OF REPAIRS				5,725.56

Report Ref No. CC4/LPC22012956/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 9905S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 9905S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

