

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

85763 - C00001 SL: SERVICE SALES - PC
Mr BS Azmi Bin Saaïd
21 Jalan Punai

Singapore 418800

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Azmi Bin Saaïd

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 29/12/2022
WIP No. . : 56691
Veh.In/Out:
*Tel.No. . : Mobile: 98622930
Reg.No. . : SLD99058
Reg.date . : 01/07/2016
Mileage ... : 0
Chassis No: SALCA2AG2GH564495

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE SIDE MIRROR ASSY	0 1300	1500.00	0		1,500.00	S
LH, FRT WINDSCREEN MLDG LH							
800	TO SPRAY RH SIDE MIRROR COVER,	0 1700	2200.00	0		2,200.00	S
RH A PILLAR, RH F DOOR							
280	TO CHECK WIRING INCLUDE	0	621.00	0		621.00	S
RESETTING OF ALL ELECTRICAL							
MODULES							
	MIRROR - REAR VIEW - <i>bro</i>	1.0 EA	1007.50	906.75		1,007.50	S
	COVER - MIRROR HOUSING <i>ms</i>	1.0 EA	229.20	206.28		229.20	S
	LAMP - EXTERIOR MIRROR <i>ca</i>	1.0 EA	214.10	192.69		214.10	S
	MIRROR MOTOR LH MEMO <i>ca</i>	1.0 EA	349.80	314.82		349.80	S
	GLASS - REAR VIEW OUT <i>bro</i>	1.0 EA	317.20	285.48		317.20	S
	LAMP - EXTERIOR MIRROR <i>ca</i>	1.0 EA	220.60	198.54		220.60	S
	MOULDING - DOOR WIND <i>X</i>	1.0 EA	355.90			355.90	S
	FINISHER - 'A' PILLAR <i>X</i> XNN	1.0 EA	231.00			231.00	S

Gross Total. 7,246.30

Labour Total 4,321.00
Parts Total 2,925.30
Package Total 0.00

Net..... 7,246.30
GST @ 7.0% 507.24
Total..... 7,753.55
Paid..... 0.00
Please Pay.. 7,753.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated