

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 04 Jan 2023

Preliminary Advice

Vehicle No	: SDH681U	Accident Date	: 11/12/2022
Make	: BMW 640I	Policy No.	: SP2001192609-01
Assignment Date	: 29/12/2022	Excess	: S\$800.00
Date of Inspection	: 03/01/2023	Est. Duration of Repair	: 3
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,410.60
Revised Amount	:S\$	8,139.10
Check Items (Estimated)	:S\$	610.50
Total	:S\$	8,749.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	37,147.00
Salvage Value	:S\$	
Margin for Repair	:S\$	100,853.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :*the vehicle repair on part by parts basis.due to no second parts available.*
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.