



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012962/Kwy3e2 Date: 16/01/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 2479M	Veh. Inspected	SKV 4734T	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0019	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	29/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU FORESTER (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JF1SJGK85FG055671	Colour	METALLIC GOLD	
Odometer	46833 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	YOKOHAMA	8 mm	
L/H Front Tyre	225/55 R18	YOKOHAMA	8 mm	
R/H Rear Tyre	225/55 R18	YOKOHAMA	8 mm	
L/H Rear Tyre	225/55 R18	YOKOHAMA	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/12/2022	Inspection Date	29/12/2022	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 19 SEP 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	