



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012964/Kvy3e2 Date: 19/07/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLV 2235T	Veh. Inspected	SNB 618S	
Policy No.		Coverage (\$)	0.00	
Claim No.	BVS23/0005	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	29/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	NHP1707180979	Colour	METALLIC BLACK	
Odometer	180605 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WEST LAKE	8 mm	
L/H Front Tyre	185/60 R15	WEST LAKE	8 mm	
R/H Rear Tyre	185/60 R15	WEST LAKE	2 mm	
L/H Rear Tyre	185/60 R15	WEST LAKE	2 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/12/2022	Inspection Date	29/12/2022	
Survey held at	Sin Ming Industrial Sector C #01-135			
Repairer	A T AUTO CONSULTANT			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 11 NOV 2020 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		