ASS. REC. BY:	110129641KV
Kenneth	SIGNMENT
From: Date:	
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD //P/WS/TP RES/OD RES/EVA/INV/MV	Make: Tay Sienta c.c 1896
To Inspect Vehicle No:	
at Workshop m/s	Colour M. Black A/C: Insured / Std / NI / NA
of	Sp.Reading 180605 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: NIAPIFO . 7180979
Claims No.	Gen. Cohd; Good) Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / 8/Rim / STD A/Rim or
	Tyre Size: F: 185/60R15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or West // a //e
Bal. or Market Value: 8/10/	
IDAC Accident Rport: Consistent? : Yes or No	Fron! Rear
GIA / PR Seen: Consistent? : Yes or No	R/Bal. 0 mm R/Bal. 2 mm
Est. Repairs: 12-15 days Res.: Yes or No	L/Bal. / mm L/Bal. 2 ITIM
1	D.O.A. 26/12/22 D.O.I. 29/12/202
	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Tail sake jammed	
2	
8	
Data/Time, File Pass to?	
Da Da	ys Of Repair:
: Final Report Re	survey No. of Trip: Survey Fee
Outs/Time, File Return to?	
Add Fee:	: Site Insp (\$
	//
eport Format :	: Interview (\$) Firsts
	Tech love (\$
ump Sum / I.B.I: (S	
	Weekend (\$

Not Notherial 1.B.1 Menny Bypain

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113 HP: 8386 8989 EMAIL: atautoconsultant@gmail.com Co. Reg. No. : 53368526E

Date of Estimate: 27.12.2022 Vehicle No: SNB618S Owner: **EAGERNESS** Date of Accident: 24.12.2022

Make & Model: TOYOTA SIENTA 7 SEATER 1.5

Chassis No : NHP1707180979

Chass			
PARTS	MATE FOR ACCIDENT VEHICLE NOS SNB618S		B 41 107 00 /
	1 1 Tailgate		\$1,197.00
2	2 2 Tailgate reflector RH/LH	@	\$235.00 cm \$470.00 \ \(\sigma_{\text{a}} \) \$495.00 \(\sigma_{\text{b}} \)
3	1 Tailgate lock		* \$45.00 <u></u>
4	1 Tailgate striker		Bu \$325.00
5	First St. Constitution		Ma \$185.00
6			Pallar \$398.00
7	1 Tailgate weatherstrip		Ma \$88.00 -
8	1 Tailgate emblem logo "TOYOTA"		ne \$75.00
9	1 Tailgate emblem "HYBRID"		M CM \$293.00
10	1 Tailgate handle moulding		\$702.00 7
11	1 Tailgate wiper motor		\$89.00 X
12 13	1 Tailgate wiper arm	K in a	\$88.00 7
14	1 Tailgate number plate lamp		\$261.00 \$552.00 7
15	2 Tailgate absorber LH/RH 2 Taillamp RH/LH	cas 0/17 @	\$368.00 \$736.00
16	2 Taillamp pillar outer top RH/LH	NISCRA @	\$210.00 \$420.00
17		NIA @	\$196.00 \$392.00
18	2 Taillamp pillar outer lower RH/LH 2 Taillamp pillar inner RH/LH	@	\$236.00 \$472.00 7
19		٣	Ry \$553.00
20	The state of the s		\$333.00
	1 Rear bumper center garnish		
21	2 Rear bumper side garnish LH/RH thto earne the little RH LK Auto Consultation and the little RH	@	
22	2 Rear bumper side retainer outer LH/RH	@	7200.00 7210.00
23	2 Rear bumper side retainer inner LH/RH	@	7.5.66
24	1 Rear bumper retainer inner garnish		\$68.00 7
25	2 Rear bumper reflector RH/LH	@ (a = 1)	\$98.00 % \$196.00 X
26	1 Rear wheel arch garnish RH/LH	NISDIY @	
27 you	1 Rear fender RH/LH	MI Hu @	\$1,100.00 \$2,200.00
28	1 Rear fender inner garnish RH/LH	@	\$756.00 \$1,512.00 7
29	1 Rear fender air vent RH/LH	@	
30	2 Rear door rail RH/LH	@	
31	2 Rear door rail top garnish RH/LH	@	
32	1 Rear end panel outer	<u>u</u>	
33	1 Rear end panel inner		\$489.00
34	1 Rear end panel top garnish		My \$725.00 -
			n~ \$235.00 —
35	1 Remote key sensor		\$189.00 7
36	1 Remote key sensor harness		\$423.00 7
37	1 Rear floor panel		
38	1 Rear floor tow pin support panel		\$754.00 7
39	1 Rear luggage tray		\$165.00 7
	Page	l of 2	\$478.00 7

40 2 Rear luggage tray top cover RH/LH					
1 Rear floor panel under cover \$3365.00 7 1 Rear floor panel linner top cross member \$1,197.00 7 1 Rear floor panel linner top cross member \$1,197.00 7 1 Rear chassis member RH/LH	40	2 Rear luggage tray top cover RH/I	.н @	\$156.00	
42 1 Rear floor panel inner top cross member 43 2 Rear chassis member RH/LH 43 2 Rear wheel arch panel RH/LH 44 2 Rear wheel arch panel RH/LH 45 1 Exhuast muffler 46 4 Exhuast muffler rubber 47 2 Rear sliding door Rh/LH (repair) SUB TOTAL LESS 25% DISCOUNTED SUB TOTAL 2 Iset Rear bumper clips 3 1 Set Rear number plate & garnish 4 1 Reverse cam 5 1 Advertisement sticker 6 1 Tyre rear RH 7 1 Battery rear mount SUB TOTAL LESS 0% DISCOUNTED SUB TOTAL LESS 0% DISCOUNTED SUB TOTAL SUB TO	41				
43 2 Rear chassis member RH/LH 44 2 Rear wheel arch panel RH/LH 45 1 Exhuast muffler 46 4 Exhuast muffler rubber 47 2 Rear sliding door Rh/LH (repair) 8	42		member		
44 2 Rear wheel arch panel RH/LH 45 1 Exhuast muffler 46 4 Exhuast muffler rubber 47 2 Rear sliding door Rh/LH (repair) 8	43	•			The state of the s
45 1 Exhuast muffler rubber 46 4 Exhuast muffler rubber 47 2 Rear sliding door Rh/LH (repair) SUB TOTAL LESS 25% DISCOUNTED SUB TOTAL SS. NETT ITEM 1 1set Rear bumper clips 2 1set Reverse sensor 3 1set Rear number plate & garnish 4 1 Reverse cam 5 1 Advertisement sticker 6 1 Tyre rear RH 7 1 Battery rear mount SUB TOTAL LESS 0% DISCOUNTED SUB TOTAL LESS 0 % DISCOUNTED SUB TOTAL S3,200.00 S1,480.00 S4,00.00 S1,480.00 S4,00.00 S1,480.00 S2,00.00	44		@ 1	\$566.00	St. March 1997 March 1998
A7 2 Rear sliding door Rh/LH (repair) \$1,800.00 \$23,860.00 \$23,860.00 \$5,965.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$17,895.00 \$18,000 \$1	45	1 Exhuast muffler			
Sub Total Sub	46	4 Exhuast muffler rubber	@	\$25.00	The state of the s
S. NETT ITEM	47	2 Rear sliding door Rh/LH (repair)			March Control of the
1			LESS 25%		\$5,965.00
1	S. NETT IT	<u>EM</u>			10 45000
1 Panel beating for replace and repair affected parts \$2,400.00 \$3,200	1	1set Rear bumper clips			1 \$50.00 -
1 Reverse cam \$220.00 7 1 Advertisement sticker \$320.00 7 1 Battery rear RH \$320.00 7 2 SUB TOTAL \$1,480.00 1 LESS 0 % \$0.00 5 LESS 0 % \$1,000 6 Remove/refix 2nd & 3rd row seats to facilitate the repair \$300.00 6 Remove/refix tailgate components \$1,000 \$600 8 Remove/refix tailgate windscreen \$250.00 \$200.00 9 Remove/refix fender quarter glass \$200.00 \$600 6 Remove/refix fender quarter glass \$200.00 \$600 7 Remove/refix fender quarter glass \$200.00 \$600 8 Remove/refix fender quarter glass \$200.00 \$600 9 Remove/refix fender quarter glass \$200.00 \$600 1 1 1 1 1 1 1 1 1	2	1set Reverse sensor			B + + + + + + + + + + + + + + + + + + +
1 Reverse cam	3	1set Rear number plate & garnish			
\$320.00 7 1 Tyre rear RH 2 1 Battery rear mount SUB TOTAL LESS 0 % DISCOUNTED SUB TOTAL S1,480.00 \$1,480.	4	1 Reverse cam			\$220.00 T
Tyre rear RH	5	1 Advertisement sticker			
SUB TOTAL LESS 0 % DISCOUNTED SUB TOTAL Panel beating for replace and repair affected parts Spray painting on accdient areas Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass SUB TOTAL S1,480.00 \$0.00 \$1,480.00 \$1,480.00 \$2,400.00 \$2,400.00 \$2,400.00 \$2,400.00 \$3,200.0	6	1 Tyre rear RH			The second secon
SUB TOTAL LESS 0 % DISCOUNTED SUB TOTAL Panel beating for replace and repair affected parts Spray painting on accdient areas Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix tailgate windscreen Remove/refix fender quarter glass	7	1 Battery rear mount			
LABOUR 1 Panel beating for replace and repair affected parts 2 Spray painting on accdient areas 3 Wiring charges 4 Apply undercoating to above affected areas 5 Remove/refix 2nd & 3rd row seats to facilitate the repair 6 Remove/refix reverse sensor 7 Remove/refix tailgate components 8 Remove/refix tailgate windscreen 9 Remove/refix fender quarter glass \$1,480.00 \$3,200.00 \$2,400.00 \$2,400.00 \$2,400.00 \$3,200.00 \$3,200.00 \$3,200.00 \$3,00.00 \$3			SUB TOTAL		
Discounted sub total Panel beating for replace and repair affected parts Spray painting on accdient areas Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix reverse sensor Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass					
Panel beating for replace and repair affected parts Spray painting on accdient areas Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix reverse sensor Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass \$3,200.00			DISCOUNTED SUB TOTAL		32,400.00
Panel beating for replace and repair affected parts Spray painting on accdient areas Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix reverse sensor Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass \$3,200.00	LABOUR				
Spray painting on accdient areas Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix reverse sensor Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass \$2,400.00 Remove/refix \$100.00 Formation \$2,400.00 Formation \$100.00 Formation \$2,400.00 Formation \$100.00 Formation \$2,400.00 Formation \$100.00 Formation \$2,400.00 Formation \$20.00 Formation \$2,400.00 Formation \$20.00 Formation \$2,400.00 Formation \$20.00 Fo		Panel beating for replace and repair a	ffected parts		
Wiring charges Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix reverse sensor Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass \$100.00 201 \$120.00 501 \$200.00 601					
Apply undercoating to above affected areas Remove/refix 2nd & 3rd row seats to facilitate the repair Remove/refix reverse sensor Remove/refix tailgate components Remove/refix tailgate windscreen Remove/refix fender quarter glass \$120.00					\$100.00 201
5 Remove/refix 2nd & 3rd row seats to facilitate the repair 6 Remove/refix reverse sensor 7 Remove/refix tailgate components 8 Remove/refix tailgate windscreen 9 Remove/refix fender quarter glass \$300.00 \$50.00 \$50.00 \$60.00 \$		A CONTRACTOR OF THE CONTRACTOR	areas		
6 Remove/refix reverse sensor \$50.00 \(\sigma_{\text{ol}} \) 7 Remove/refix tailgate components \$100.00 \(\beta_{\text{ol}} \) 8 Remove/refix tailgate windscreen \$250.00 \(\left_{\text{ol}} \) 9 Remove/refix fender quarter glass \$200.00 \(\beta_{\text{ol}} \)	-				\$300.00 154
7 Remove/refix tailgate components \$100.00 602. 8 Remove/refix tailgate windscreen \$250.00 /2 0 9 Remove/refix fender quarter glass \$200.00 607					
8 Remove/refix tailgate windscreen \$250.00 /2 or \$250.00 /2 or \$250.00 /2 or \$250.00 /2 or \$200.00 60/					
9 Remove/refix fender quarter glass \$200.00 601					
				1 11/2 11.	
SUB TOTAL (LABOUR) \$6,720.00	9	Remove/refix fender quarter glass	atomic lighter than some		
			SUB TOTAL (LABOUR)		\$6,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SC1N22CS0004 / City Auto Pte Ltd ENTRY DATE & TIME: 28/12/2022 16:20 (SGT) SUBMITTED BY: Jason Quak VERSION: 1 (28/12/2022 16:20 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information provided must be as truthful and accurate as possible. Any willul misrepresentation of misrosis.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving on that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/12/2022 16:20 (SGT)
Reported by	Driver (CCT)
Date of Accident	24/12/2022 10:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CHANGI AIRPORT T2 BLVD
Country/State of Loss	Singapore

DETAILS OF	OWN VEHICLE
Vehicle Registration Number INSURED/POLICYHOLDER	SNB618S
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	Yes EAGERNESS 5332663E FUJI001991@GMAIL.COM (Phone) +65-96894955
VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of	Toyota Sienta

No - Claiming third party

Private hire

Auto 1500

INSURANCE COMPANY

Vehicle Category

Transmission

Name of Insurance Company	 Income Insurance Limited
Policy Number / Cover Note Number	 5119676451-02

DRIVER

Name of Driver	···· ···· ··· ·· ··· ··· ··· ··· ··· ·	NG HOCK KEE
NRIC No		S1505088H
Data Of Birth		16/04/1961
Occupation	· · · · · · · · · · · · · · · · · · ·	Outdoor

Are you claiming under your own insurance policy for repair to your vehicle?

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthil and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>recordate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for Investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurence Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
 report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyors/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (i) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable taw in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their tawyers/taw firms), which may be sited outside of Singapore, for one or more of the above Purposes.

600

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Oate & Time

CITY AUTO PTE LTD

Blk 8 Sin Ming Road #01-58/50/62 Sin Ming Ind Est Singapore 575643

Witnessed by Reporting Centre Personnel (Name as in NRICAD card)

Sketch Plan

