

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 27.12.2022
Vehicle No: SNB618S
Owner: EAGERNESS
Date of Accident: 24.12.2022
Make & Model: TOYOTA SIENTA 7 SEATER 1.5
Chassis No : NHP1707180979
SUPPLEMENTARY ESTIMATE FOR ACCIDENT VEHICLE NOS SNB618S

PARTS

- | | | |
|---|---|-------------------------------------|
| 1 | 1 | Tailgate inner handle garnish |
| 2 | 1 | 3rd row seat under cover |
| 3 | 1 | 3rd row seat under support bar |
| 4 | 4 | Floor panel top steel plate bracket |
| 5 | 1 | Battery bracket |
| 6 | 2 | 3rd seat LH/RH @ 2150 |
| 7 | 1 | 3rd row safety belt LH |
| 8 | 1 | Exhaust heat shield |

SUB TOTAL
LESS 25%
DISCOUNTED SUB TOTAL

Ret	\$85.00	✓
Ret	\$423.00	✓
Ret	\$235.00	✓
Ret	\$140.00	✓
Ret	\$125.00	✓
Dis 1 Ret	\$5,490.00	✓
TM	\$786.00	✓
Ret	\$189.00	✓
	<u>\$7,473.00</u>	
	<u>\$1,821.00</u>	
	<u>\$5,652.00</u>	