

ASS. REC. BY:

REF:

AIG/22012965/kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

28/12 11:00 @ 25501 Cab

Veh No:

S110 495P

Yr Regn:

11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

C.C.

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

539635

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 283508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/12/22

D.O.I.

22/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD495P*Not Authored*
*11/12/2022***AAD2212-**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

22 DEC 2022**SHD495P**

VF1ABL15AUC283508

200303878K

RENAULT

LATITUDE

21/12/2022

SMV407R/AIG

30/11/2017

PART**LIST**

1	BUMPER COVER FRT	\$	<i>As</i>	747.20	✓
1	BUMPER BRACKET KIT FRT RH	\$	<i>Sm</i>	101.40	X
1	BUMPER RETAINER FRT RH	\$	<i>cm</i>	101.40	✓
1	FENDER PANEL FRT RH	\$	<i>R</i>	437.10	✓
1	WHEELARCH FRT RH	\$	<i>T</i>	191.40	✓
1	WIPER RESERVOIR	\$	<i>pu</i>	179.60	✓
1	HEADLAMP RH	\$	<i>cm</i>	743.60	✓
1	DOOR PANEL FRT RH	\$	<i>n</i>	2,844.66	X
1	DOOR HINGE UPPER FRT RH	\$	<i>n</i>	261.28	X
1	DOOR HINGE LOWER FRT RH	\$	<i>n</i>	300.55	X
		\$		5,908.18	
		10% \$		590.82	
		\$		5,317.36	

Special Nett

1	FRONT BUMPER CLIP	\$	<i>Mr</i>	66.00	✓
1	RIM	\$	<i>Sm</i>	350.00	X
1	TYRE	\$	<i>Sm</i>	300.00	X
1	FENDER LINER CLIP	\$	<i>Mr</i>	65.00	✓
1	DOOR STICKER TRANSCAB	\$	<i>an</i>	100.00	X
1	DOOR STICKER TEL NO.	\$	<i>an</i>	100.00	X
1	DOOR ADVERTISEMENT	\$	<i>an</i>	200.00	X
	TOTAL	\$		1,181.00	
	TOTAL PARTS	\$		6,498.36	

LABOUR**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD495P**AAD2212-**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i>	300.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	<i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	<i>4001</i>
To Rust-Proofing Of The Affected Areas.	\$		170.00	<i>301</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
TOTAL	\$		7,880.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD495P

AAD2212-

Over All Total	\$	<u>19,695.73</u>
----------------	----	------------------

(LUMP SUM)

Repair Days

~~5~~ DAYS

2 days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD495P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Dec 2022
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003260
Chassis No.:	VF1ABL15AUC283508
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$13,998.00

Intended COE Rebate Details

COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$12,341.00
Total Rebate Amount:	\$26,339.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Dec 2022

OK