



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC22000769/Dny3e2-1

Date: 04/01/2023

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCY 1581R	Veh. Inspected	SY 9311L
Policy No.		Coverage (\$)	0.00
Claim No.	22/22/22/VP05/025389	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	24/12/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2050402R083591	Colour	SILVER
Odometer	107437 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/01/2022	Inspection Date	24/01/2022
Survey held at	TECK SIANG MOTOR SERVICE BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-331. SINGAPORE 569537		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**