

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI22012969/KVP3M4**Date:** 03/01/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT109198	
<b>Claimant Vehicle No :</b>	SHB7678T	<b>Insured Vehicle No :</b>	SMF6823S	
Date of Loss:	09/12/2022	Nature of Claim:	TP	Claim No: M2207033

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB7678T</b>	Engine No:	2ZR2C02869
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU003079506
Reg. Date:	22/03/2019 (Man. Year: 2018)	Odometer:	333971 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Wanli 9 mm	Rear Right Side:	Sailun 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,756.02	1,738.95	3,017.07	63.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,540.00	2,050.00	57.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,346.02</b>	<b>3,278.95</b>	<b>5,067.07</b>	<b>60.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	8,346.02	2,600.00	5,746.02	68.85
<b>+ GST 7.00/7.00% (S\$)</b>	584.22	182.00	402.22	68.85
<b>Nett Amount (S\$)</b>	<b>8,930.24</b>	<b>2,782.00</b>	<b>6,148.24</b>	<b>68.85</b>

INSPECTION

Date of Assignment:	29/12/2022	
Date Inspected:	19/12/2022	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7678T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY, REAR DOOR, LH	Bent	1,294.90 FL	*1,294.90 FL
2	1		*FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	Serviceable	193.50 FL	*- FL
3	1		*COVER, REAR DOOR OUTSIDE HANDLE, LH	Serviceable	17.90 FL	*- FL
4	1		*HINGE ASSY, REAR DOOR, LOWER LH	Repair	87.10 FL	*- FL
5	1		*HINGE ASSY, REAR DOOR, UPPER LH	Repair	98.90 FL	*- FL
6	1		*TAPE, BLACK OUT, NO.1 REAR LH	Necessary	21.90 FL	*21.90 FL
7	1		*TAPE, BLACK OUT, NO.2 REAR LH	Necessary	34.90 FL	*34.90 FL
8	1		*TAPE, BLACK OUT, NO.3 REAR LH	Necessary	15.40 FL	*15.40 FL
9	1		*PANEL SUB-ASSY, QUARTER, LH	Bent	871.50 FL	*871.50 FL
10	1		*PANEL SUB-ASSY, QUARTER WHEEL HOUSE, INNER LH	Repair	544.00 FL	*- FL
11	1		*LINER, REAR WHEEL HOUSE, LH	Serviceable	139.80 FL	*- FL
12	1		*MOULDING ASSY, BODY ROCKER PANEL, LH	Repair	594.80 FL	*- FL
13	1		*RIM	Serviceable	1,900.10 FL	*- FL
14	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
15	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
16	1		*FRT DOOR STICKER TRANSCAB	Not Necessary	100.00 FS	*- FS
17	1		*REAR DOOR STICKER TEL. NO	Necessary	100.00 FS	*60.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	6,209.70 2,298.60
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,453.68 559.65
					Total Parts (S\$)	4,756.02 1,738.95

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	100.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,400.00	700.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	660.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>3,590.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >