

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD	Ref:	<del>C00/LPC22008207/y9</del> CS3/LPC22008207/Rqy3-1	
	300 BEACH ROAD #17-04/07 THE CO	) NCOURSESINGAPORE 199555	Date:	25/08/2022	
			Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBF 189J	Veh. Inspected	FBT 2275G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	<del>25/08/2022</del> 27/12/2022	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer -		Steering		
	Brakes		Modification		
	General				
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.	<del>_</del>				
	Accident Date	24/08/2022	Inspection Date		
	Survey held at	71 Woodlands Industrial Park #01-18 WAVE 9			
	Repairer	SPORTS MOTOR PTE LTD			
5a.					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				