



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22008207/Rqy3e2-1 Date: 24/04/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 189J	Veh. Inspected	FBT 2275G	
Policy No.	Z22VC05012103	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026201	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	27/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA NC750XA	c.c	745	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JH2RH09A9MK005212	Colour	MULTI COLOUR	
Odometer	14766 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	DUNLOP	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60Z R17	DUNLOP	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/08/2022	Inspection Date	29/08/2022	
Survey held at	71 Woodlands Industrial Park #01-18 WAVE 9			
Repairer	SPORTS MOTOR PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	