

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHA2483B/28/12/2022 15:23	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER RH <i>LA</i>	25.00	0.00	*1,111.93 FL
2	1		*FRT FENDER EMBLEM RH <i>ne</i>	25.00	0.00	*86.50 FL
3	1		*FRT DOOR ASSY RH <i>bt</i>	25.00	0.00	*1,264.00 FL
4	1		*REAR DOOR ASSY RH <i>repair</i>	25.00	0.00	× *1,258.30 FL × <i>R</i>
5	1		*ROCKER PANEL GARNISH RH <i>sea</i>	25.00	0.00	*576.00 FL
6	1		*REAR BUMPER ASSY <i>de</i>	25.00	0.00	*503.04 FL
7	10		*REAR BUMPER CLIPS <i>ne</i>	25.00	0.00	*22.00 FL
8	1		*REAR BUMPER MAT <i>ne</i>	0.00	0.00	*50.00 F
9	1		*REAR BUMPER CENTRE MOULDING <i>sea</i>	25.00	0.00	*654.96 FL
10	1		*REAR BUMPER SIDE UNDER COVER RH <i>de</i>	25.00	0.00	*232.00 FL
11	1		*SEAL REAR BUMPER SIDE RH <i>de</i>	25.00	0.00	*148.40 FL
12	1		*TAILAMP ASSY UPPER RH <i>ca</i>	25.00	0.00	*557.90 FL
13	1		*TAILAMP ASSY LOWER RH <i>ca</i>	25.00	0.00	*570.00 FL
14	1		*REAR BUMPER TOW COVER <i>xnn</i>	25.00	0.00	*82.70 FL ×
15	1		*REAR BUMPER BEAM <i>xnn</i>	25.00	0.00	*378.32 FL ×
16	1		*REAR BUMPER SIDE BRACKET RH <i>xnn</i>	25.00	0.00	*112.70 FL ×
17	1		*REAR WHEEL RIM CAP RH <i>sea</i>	25.00	0.00	*177.70 FL
18	1		*FRT DOOR COMFORT LOGO <i>ne</i>	0.00	0.00	*75.00 F
19	1		*REAR DOOR APPS LOGO <i>ne</i>	0.00	0.00	*80.00 F

F=Franchise part. L=List/ItemDisc.

Sub Total (S\$)	<i>5904.43</i>	7,941.45
- List Item Discount on L Items (S\$)	<i>256</i>	1,934.11
Total Parts (S\$)	<i>4428.32</i>	6,007.34

ComfortDelGro Engineering Pte Ltd/SHA2483B/28/12/2022 15:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

*205 **

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

11

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

1400

1,500.00

2 SPRAYPAINT

New

1375

1,500.00

3 CHECK WIRING

New

30

50.00

4 TUFF KOTE

New

50.00

50.00

5 TRANSFER DOOR PARTS

New

60

240.00

6 REMOVE/REFIX REVERSE SENSOR

New

40

50.00

7 TOWING FEE - KING DOLLY *receipt*

New

Xna ?

150.00 X

Gross Labour Cost (S\$)

3,540.00

ComfortDelGro Engineering Pte Ltd/SHA2483B/28/12/2022 15:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

4428.32

205.00

11.00

2955.00

7599.32

206

6079.45

45- \$6,100

Paul

H# 90010068

8 days

45

28/12/22

@1600

Resy after
repair