

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 32716

Accident Date : 27-Dec-2022

Date : 29-Dec-2022

Our Ref : 022486 / SANDRA

PAGE : 1

GREAT AMERICAN INSURANCE COMPANY

3 TEMASEK AVE #16-01

CENTENNIAL TOWER

Singapore 039190

ESTIMATED COST OF REPAIR FOR TOYOTA DYNA 3.0 DIESEL TURBO (2016) GBE6091Y

1 pc	LH front pillar - outer	225.00 c
1 pc	LH rear pillar - outer	295.00 c
1 pc	LH front door	630.00 c
1 pc	LH front door weatherstrip	95.00 c
1 pc	LH front door frame weatherstrip	105.00 c
1 pc	LH front door front seal	55.00 c
1 pc	LH front door lower seal	50.00 c
1 pc	LH front door checker	75.00 c
1 pc	LH front door checker bracket	38.00 c
1 pc	LH front door chekcer pin	10.00 c
1 pc	LH front door top 1/4 garnish	75.00 c
1 pc	LH front door window glass	240.00 c
1 pc	Lh front door window glass run channel	115.00 c
1 pc	LH front door window glass run channel frame	80.00 c
1 pc	LH front door window glass outer moulding	110.00 c
1 pc	LH front door window glass regulator	150.00 c
1 pc	LH front door window glass regulator motor	260.00 c
1 pc	LH front door hinges - top	55.00 c
1 pc	LH front door hinges - bottom	55.00 c
1 pc	LH front door lock	195.00 c
1 pc	LH front door lock catch	35.00 c

Con't Page 2 ...

Press any key to continue...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Page : 2

No. : 32716

Our Ref : 022486

1 pc	LH front door lock actuator	95.00 c
1 pc	LH front door outer handle	85.00 c
1 pc	LH front door inner handle	190.00 c
1 pc	LH front door inner trim	380.00 c
1 pc	LH front door signallamp	55.00 c
1 pc	LH front door speaker	195.00 c
1 pc	LH front door step garnish	125.00 c
1 pc	LH front door inner wheel arch garnish	65.00 c

4,138.00

Add 10% : 413.80

4,551.80

1 pc LH front door ROC sticker 25.00 sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts. 800.00

To remove door's fittings 80.00

To putty and respray on affected
portions. 750.00

Total : S\$ 6,206.80

Singapore Dollars SIX THOUSAND TWO HUNDRED SIX
AND CENTS EIGHTY Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.