

ASS. REC. BY:

REF:

A151

## ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMZ 64756

Yr Regn:

05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

c.c

Colour

n-Blue

A/C: Insured / Std / NI / NA

Sp. Reading

53789

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report  
☐ : Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Transportation

S - RS. SI

Parking

Others

Report Format:

Sum / I.B.I. (\$)

TOTAL

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003362215-01	Date of Loss:	23/12/2022
Vehicle Reg. No.:	<b>SML6475G</b>	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WEIXIANG HENRY ANG	Contact No:	+6594888486
Driver:	WEIXIANG HENRY ANG		

Make/Model:	HONDA FREED HYBRID, 1.5 (A)	Vehicle Reg. Date:	29/05/2019
Vehicle Colour:	BLUE	Chassis No:	GB71087435
Engine No:	LEB5625468		
Odometer:	53782 KM		

Paint Type: NO  
 Total Loss? *14 days*  
 Est. Duration of Repair (day)

Description of Accident/Loss: PLEASE REFER TO  
 Present Location: ELITE AUTOMOTIVE PTE LTD (HQ)

*Not Notified*  
*LI Rep &*  
*Henry After Rain*  
*Ex 8600L*  
*Kennoth (LKK)*  
*96910663*

**COST OF CLAIMS**

	Amount
Parts	11,426.80
Miscellaneous Items	60.00
Labour	4,380.00
Paintwork Labour	0.00
Towing	0.00
<b>Calculated Gross Total (S\$)</b>	<b>15,866.80</b>
<b>- Excess (S\$)</b>	<b>600.00</b>
<b>(S\$)</b>	<b>15,266.80</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,068.68</b>
<b>Nett Amount (S\$)</b>	<b>16,335.48</b>

This claim is handled by: **HANG PEK CHIN**

Generated using Myeimen e-Claims Internet Estimation & Adjusting System

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# DETAILS

Source:

MRM-SG

Version: 1.0 (Last Synchronised: 28 Dec 2022)

HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Model:

M1-MPV

(Price-denominated Standard List)

Labour:

Repairer's

Print Code: (Unsubmitted, no print-code for SML6475G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	<i>B</i> *580.00 F <i>—</i>
2	2		*BONNET HINGES (LH & RH)	0.00	0.00	<i>B</i> *100.00 F <i>—</i>
3	1		*BONNET INSULATION	0.00	0.00	<i>Sn</i> *80.00 F <i>X</i>
4	10		*BONNET INSULATION CLIPS	0.00	0.00	<i>nn</i> *30.00 F <i>X</i>
5	1		*BONNET STAND	0.00	0.00	<i>n</i> *35.00 F <i>X</i>
6	1		*BONNET STAND CLIP	0.00	0.00	*5.00 F <i>?</i>
7	1		*BONNET LOCK	0.00	0.00	<i>017</i> *120.00 F <i>—</i>
8	1		*FRONT BUMPER	0.00	0.00	<i>CM</i> *700.00 F <i>—</i>
9	2		*FRONT BUMPER RETAINER (LH & RH)	0.00	0.00	<i>Dis</i> *40.00 F <i>—</i>
10	10		*FRONT BUMPER CLIPS	0.00	0.00	<i>nn</i> *30.00 F <i>—</i>
11	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*380.00 F <i>?</i>
12	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	<i>Sn</i> *160.00 F <i>X</i>
13	1		*TOWING CAP	0.00	0.00	<i>n</i> *18.00 F <i>X</i>
14	1		*FRONT GRILLE	0.00	0.00	<i>CM</i> *680.00 F <i>—</i>
15	2		*HEADLAMP (LH & RH)	<i>CM</i> 0.00	0.00	*2,400.00 F <i>—</i>
16	2		*HEADLAMP LOWER BRACKET (LH & RH)	0.00	0.00	*80.00 F <i>?</i>
17	2		*FRONT FENDER (LH & RH)	0.00	0.00	<i>Bu</i> *800.00 F <i>—</i>
18	1		*AIRCON CONDENSER	0.00	0.00	*850.00 F <i>?</i>
19	1		*RADIATOR	0.00	0.00	*980.00 F <i>?</i>
20	2		*FAN COWLING	0.00	0.00	*240.00 F <i>?</i>
21	2		*FAN MOTOR	0.00	0.00	*560.00 F <i>?</i>
22	2		*FAN BLADE	0.00	0.00	*160.00 F <i>?</i>
23	1		*A/C SUCTION PIPE	0.00	0.00	<i>Sn</i> *220.00 F <i>X</i>
24	1		*A/C DISCHARGE PIPE	0.00	0.00	*260.00 F <i>?</i>
25	1		*A/C LIQUID PIPE	0.00	0.00	*280.00 F <i>?</i>
26	1		*SUPPORT PANEL	0.00	0.00	<i>B</i> *600.00 F <i>—</i>

F=Franchise part.

Sub Total (S\$)	10,388.00
+ Margin on L,N Items 10.00% (S\$)	1,038.80
<b>Total Parts (S\$)</b>	<b>11,426.80</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

# on Miscellaneous Items Particulars

Amount

## 1 Miscellaneous Items

FRONT NUMBER PLATE WITH HOLDER

60.00 X

Sub Total (S\$)

60.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

### Labour Items

1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	New	1,800.00
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT BOTH FENDER, SUPPORT PANEL, FRONT BOTH A PILLAR	New	1,800.00
3	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	New	280.00
4	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS, TO VACUUM & CHARGE UP GAS.	New	150.00
5	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	New	200.00
6	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIR. INCLUDING PRESSURIZE COOLING SYSTEM.	New	150.00

Gross Labour Cost (S\$)

4,380.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

## Enquire PARE/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 811B

### Vehicle Details

Vehicle No.: SML6475G

Vehicle to be Exported: No

Intended Deregistration Date: 28 Dec 2022

Vehicle Make: HONDA

Vehicle Model: FREED HYBRID 1.5G AUTO

Primary Colour: Blue

Manufacturing Year: 2018

Engine No.: LEB5625468

Chassis No.: GB71087435

Maximum Power Output: 101.0 kW (135 bhp)

Open Market Value: \$26,986.00

Original Registration Date: 29 May 2019

First Registration Date: 29 May 2019

Transfer Count: 1

Actual ARF Paid: \$19,781.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 May 2029

PARF Rebate Amount: \$14,835.00

### Intended COE Rebate Details

COE Expiry Date: 28 May 2029

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$43,102.00

COE Rebate Amount: \$27,657.00

**Total Rebate Amount: \$42,492.00**

The information contained herein is correct as at 28 Dec 2022

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.  
2. This Form must be completed by the Policyholder and/or the Actual Driver.  
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.  
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.  
5. Any false reporting may be referred to the Police for investigation.  
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.  
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	24/12/2022 11:39 (SGT)
Reported by	Both
Date of Accident	23/12/2022 17:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE AFTER STEVEN ROAD EXIT
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML6475G
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WEIXIANG HENRY ANG
NRIC No	SXXXX811B
Email Address	hot_hawx@hotmail.com
Mobile Phone No	(Phone) +65-94888486
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Freed
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1496


### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003362215-01

### DRIVER

Name of Driver	WEIXIANG HENRY ANG
NRIC No	SXXXX811B
Date Of Birth	30/05/1982
Occupation	Indoor

ETCH PLAN



Vehicle A: 8ML 6475G

B: GBE 7926H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on PIE towards Tuar. After the Stevens Road exit, a lorry GBE 7926H suddenly jammed its brakes in front of me. Its right rear brake light was not working and I was not able to stop in time.

The lorry did not have visible damage, but my car bonnet was damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature

Date & Time 24/12 2022  
10:30 am

Driver's Signature

(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.