## Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

: 6

From: LKK Auto Consultants Pte Ltd

Attn: JANICE KOH 16 Jan 2023 Date:

# **Preliminary Advice**

Vehicle No : SML6475G Accident Date : 23/12/2022

: HONDA FREED HYBRID Policy No. Make : SP2003362215-01

Assignment Date : 29/12/2022 Excess : S\$600.00

Date of Inspection : 03/01/2023 Est. Duration of Repair

Inspection At : ELITE AUTOMOTIVE PTE LTD (HQ)

280 WOODLANDS INDUSTRIAL PARK E5, #01-17, HARVEST@WOODLANDS

SINGAPORE 757322

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,954.80 (Estimate \$15,866.80 + Supplementary \$88.00)
-----------------------------	------	--

**Revised Amount** :S\$ 11,232.00 Check Items (Estimated) :S\$ 280.00 Total :S\$ 11,512.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old	Value	:S\$

Pre-Accident Value :S\$ 104,000.00 COE / PARF Rebate :S\$ 42,492.00

Salvage Value :S\$

Margin for Repair :S\$ 61,508.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amour	it. We have also	confirmed excess	s and policy coveraເ	ge. Kindly
	let us have your authorisation.				

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.