

ASS. REC. BY:

From:

Estimated Cost:

OD/TP/WS/LTP

To Inspect Vehicle

at Workshop m

of

Insured:

Policy No.

Claims No.

Sum Ins

(Clic

Make

TAILS

MRM-SG

M1-MPV

Repairer's

Version: 1.0 (Last Synchronised: 28 Dec 2022)

HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
(Price-denominated Standard List)

Code: (Unsubmitted, no print-code for SML6475G)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Other Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET			
2	2		*BONNET HINGES (LH & RH)	0.00	0.00	B ₂ *580.00 F
3	1		*BONNET INSULATION	0.00	0.00	B ₂ *100.00 F
4	10		*BONNET INSULATION CLIPS	0.00	0.00	B ₂ *80.00 F
5	1		*BONNET STAND	0.00	0.00	B ₂ *30.00 F
6	1		*BONNET STAND CLIP	0.00	0.00	B ₂ *35.00 F
7	1		*BONNET LOCK	0.00	0.00	*5.00 F
8	1		*FRONT BUMPER	0.00	0.00	B ₁₁ *120.00 F
9	2		*FRONT BUMPER RETAINER (LH & RH)	0.00	0.00	CM ₁ *700.00 F
10	10		*FRONT BUMPER CLIPS	0.00	0.00	B ₁₁ *40.00 F
11	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	B ₂ *30.00 F
12	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*380.00 F
13	1		*TOWING CAP	0.00	0.00	B ₂ *160.00 F
14	1		*FRONT GRILLE	0.00	0.00	B ₂ *18.00 F
15	2		*HEADLAMP (LH & RH)	0.00	0.00	CM ₁ *680.00 F
16	2		*HEADLAMP LOWER BRACKET (LH & RH)	0.00	0.00	*2,400.00 F
17	2		*FRONT FENDER (LH & RH)	0.00	0.00	*80.00 F
18	1		*AIRCON CONDENSER	0.00	0.00	B ₂ *800.00 F
19	1		*RADIATOR	0.00	0.00	*850.00 F
20	2		*FAN COWLING	0.00	0.00	*980.00 F
21	2		*FAN MOTOR	0.00	0.00	*240.00 F
22	2		*FAN BLADE	0.00	0.00	*560.00 F
23	1		*A/C SUCTION PIPE	0.00	0.00	*160.00 F
24	1		*A/C DISCHARGE PIPE	0.00	0.00	B ₂ *220.00 F
25	1		*A/C LIQUID PIPE	0.00	0.00	*260.00 F
26	1		*SUPPORT PANEL	0.00	0.00	B ₂ *280.00 F
				0.00	0.00	B ₂ *600.00 F

F=Franchise part.

Sub Total (\$\$)

10,388.00

+ Margin on L,N Items 10.00% (\$\$)

1,038.80

Total Parts (\$\$)

11,426.80

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

wiper tank - \$80 ✓ nd ✓