

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: BMW 116D

Engine/Chassis No.: WBA1V72030V724308


Date of accident: 26.12.22

Damaged area: Rear

Date: 29/12/2022

Claim Type: TP

VRN: SKH713D



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 1,563.00	\$ 1,563.00
2	Tailgate weatherstrip	1	\$ 289.00	\$ 289.00
3	Rear bumper reflector	2	\$ 231.00	\$ 462.00
4	Rear bumper	1	\$ 1,295.00	\$ 1,295.00
5	Rear bumper tow hook cover	1	\$ 59.00	\$ 59.00
6	Rear bumper side retainer	2	\$ 185.00	\$ 370.00
7	Rear bumper reinforcement	1	\$ 615.00	\$ 615.00
8	Rear bumper reinforcement bracket	2	\$ 146.00	\$ 292.00
9	Rear bumper center carrier	1	\$ 282.00	\$ 282.00
Subtotal				\$ 5,227.00
List discount				5.00%
Total				\$ 4,965.65

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor holder	4	\$ 14.00	\$ 56.00
2	Reverse sensor (Factory Original)	4	\$ 180.00	\$ 720.00
3	Rear bumper clips	12	\$ 5.50	\$ 66.00
4	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 892.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.5	\$ 100.00
3	Supply spray paint material and necessary items to respray affected area / panel.	4	\$ 800.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,000.00
Estimate Grand Total			\$ 7,857.65